

ANNUAL SURVEYS.

21032. 37.2.49

No. 31 Survey held at London Date, first Survey April 27 Last Survey May 20th 1878
 No. in on the Bk Wminto Master
 Reg. Book. 31 Tonnage 280 Built at Sunderland When built 1871 10M
 By whom built Pile Owners Bullard Wmto
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock by SW

Last Survey, No. 19232 Port of Iron Classed 100A 3.77
 Present Condition of the Decks Good Treenails Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. When put on "
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

She is now in good condition and entitled to remain as classed.

Senhouse Martinide

Committee's Minute 31st, May. 1878.

Character assigned 100A

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 621 Survey held at London Date, first Survey April 15 Last Survey May 10th 1878
 No. in on the Bk Loch-na-gar Master W H Kelly
 Reg. Book. 621 Tonnage 464 Built at N Hartlepool When built 1861 7M
 By whom built Pile Owners Parish Bros
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock by SW Ballast in

Last Survey, No. 18399 Port of Iron Classed 100A 5.77
 Present Condition of the Decks Good Treenails Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Good When put on Good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

She is now in good condition and entitled to remain as classed.

Senhouse Martinide

Committee's Minute 31st, May. 1878.

Character assigned 100A

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18