

ANNUAL SURVEYS.

No. 26087 Survey held at Liverpool Date, first Survey May 28th Last Survey May 31st 1878.
 No. in on the Bark "Scottish Fairy" Master R. S. Wilson.
 Reg. Book. 396 Tonnage 751 Built at Sunderland When built 1877 - 2 mo.
 By whom built Austin Owners H. N. Ross & Co.
 Port belonging to Liverpool Destined Voyage Montreal.
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock.

Last Survey, No. 18327 Port of Liver. Classed 100 AL
 Present Condition of the Decks Good Treennails Rivets. Good 4.77.
 Waterways ✓ Breasthooks and Stems ✓ Windlass and Capstan Good
 Comings ✓ Transoms, Pointers, and Crutches ✓ Pumps ✓
 Upper Deck Beams & Fastenings ✓ Timbers of the Frame at the Openings ✓ Boats ✓
 Lower Deck Beams & Fastenings ✓ Ditto ditto at other places ✓ Masts, Yards, &c. ✓
 Planksheers ✓ Keelsons ✓ Condition, how ascertained from on board
 Sheerstrakes ✓ Clamps and Shelves ✓ Sails Good
 Topsides ✓ Ceiling ✓ Anchors, No. of 3 B - 1 S - 2 H
 Wales ✓ Rudder ✓ Cables part seen Good
 Plank (Bottom) and Counter ✓ Copper or Y.M. Cement When put on 77 Hawers and Warps and
 Engine Room Skylights ✓ Caulking of Bottom, Deck, & Waterways Good Standing and Running Rigging Sufficient
 Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.
Bottom sighted, cleaned and coated with paint & the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool June 21st - 1878 T. Shilston.
 Character assigned 100 AL. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18

No. ✓ Survey held at Liverpool Date, first Survey May 25th Last Survey May 27th 1878.
 No. in on the Ship "Naiad" Master J. Smith
 Reg. Book. 13 Tonnage 1039 Built at Liverpool When built 1876 - 5 mo
 By whom built Bowdler Owners J. B. Halmesley & Co
 Port belonging to Liverpool Destined Voyage Calcutta.
 If Surveyed Afloat or in Dry Dock Queen's Dry Dock.

Last Survey, No. 18679 Port of Liver. Classed 100 AL
 Present Condition of the Decks Good Treennails Rivets. Good 5.77.
 Waterways ✓ Breasthooks and Stems ✓ Windlass and Capstan Good
 Comings ✓ Transoms, Pointers, and Crutches ✓ Pumps ✓
 Upper Deck Beams & Fastenings ✓ Timbers of the Frame at the Openings ✓ Boats ✓
 Lower Deck Beams & Fastenings ✓ Ditto ditto at other places ✓ Masts, Yards, &c. ✓
 Planksheers ✓ Keelsons ✓ Condition, how ascertained from on board
 Sheerstrakes ✓ Clamps and Shelves ✓ Sails Good
 Topsides ✓ Ceiling ✓ Anchors, No. of 3 B - 1 S - 2 H
 Wales ✓ Rudder ✓ Cables part seen Good
 Plank (Bottom) and Counter ✓ Copper or Y.M. Cement When put on 76 Hawers and Warps and
 Engine Room Skylights ✓ Caulking of Bottom, Deck, & Waterways Good Standing and Running Rigging Sufficient
 Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.
Bottom sighted, cleaned and coated with paint & the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool June 21st - 1878. T. Shilston.
 Character assigned 100 AL. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18

11/11/11

Shottish Harry
Vivad
26084



© 2019

Lloyd's Register
Foundation