

ANNUAL SURVEYS.

No. 32 Survey held at London Date, first Survey 26th June Last Survey 27th June 18 78
 No. in on the Bk. "Galca" Master Austin
 Reg. Book. 32 Tonnage 421 Built at Cardiff When built 1866 1st mo
 By whom built Bachelor Owners Richardson & Walters
 Port belonging to Swansea Destined Voyage _____
 If Surveyed ~~Afloat~~ in Dry Dock Ratcliff Dry Dock

Last Survey, No. 13834 Port of Swan Classed _____ Years assigned. _____ Character in Register Book. *A1
 Present Condition of the Decks Good Transoms Rivets Good
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons good where seen
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides Plating _____ Ceiling good where seen
 Wales _____ Rudder good
 Plank (Bottom) and Counter _____ Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers good Cargo and Main Hatchways good Hatches _____
 General Observations, Opinion as to Class, &c. _____

With the sanction of the Committee, as per Secretary's letter to the owners, dated 20th May, 1878, the S. S. No. 3, now due, has been postponed until the vessel returns from a short voyage. - Surveyed with part of cargo on board.

She is now in good, efficient condition & eligible in our opinion to remain as classed.

Committee's Minute 12th July, 1878. H. Paulsen
 Character assigned *A1 Thos Cougdon
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. 76 Survey held at London Date, first Survey 1st July Last Survey 3rd July 18 78
 No. in on the Ship "Rangitiki" Master Milman
 Reg. Book. 76 Tonnage 1188 Built at Hull When built 1863 7th mo
 By whom built Sam'lson Owners New Zeal. Shipp. Comp^y
 Port belonging to London Destined Voyage _____
 If Surveyed ~~Afloat~~ in Dry Dock Canal Dry Dock

Last Survey, No. 19095 Port of Swan Classed _____ Years assigned. _____ Character in Register Book. *A1
 Present Condition of the Decks Good Transoms Rivets Good
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons where seen
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides Plating _____ Ceiling do
 Wales _____ Rudder (braces rebushed)
 Plank (Bottom) and Counter _____ Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways good Hatches _____
 General Observations, Opinion as to Class, &c. _____

This vessel is now in good, efficient condition & eligible in my opinion to remain as classed :-

Committee's Minute 12th July, 1878. H. Paulsen
 Character assigned *A1 Thos Cougdon
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____