

ANNUAL SURVEYS.

No. 1922 Survey held at

Date

1878

326 on the

(S.S.) Brig Margaret Sutton

Master

Nicholas Reynolds

Tonnage

197 40

Built at

York

When built

1864 or 1865

? 1866

By whom built

George Robinson & Co

Owners

George Sutton & Son

Port belonging to

York

Destined Voyage

Coasting

If Surveyed Afloat or in Dry Dock

Put in Slip

Last Survey, No.

19289

Port of

York

September 1877

Classed

A.S. 9.77

S.S. No. 3-72

S.S. No. 7.76

The present Condition of the

Decks

Good

Waterways

entirely sound, good

Comings

Free good

Upper Deck Beams & Fastenings

Free good

Lower Deck Beams & Fastenings

Free good

Planksheers

Free good

Sheerstrakes

Free good

Topsides

Free good

Wales

Free good

Plank (Bottom) and Counter

Free good

Treenails

Revised, Taper & found sound

Breasthooks and Stemson

what seen good

Transoms, Pointers, and Crutches

what seen good

Timbers of the Frame at the Openings

good

Revised

ditto at other places

good

Keelsons

as far as seen good

Clamps and Shelves

none

Ceiling

as far as seen up good

Rudder

good

Copper

When put on

Windlass and Capstan

what seen good

Pumps

two put in good

Boats

two good Order

Masts, Yards, &c.

on all good

Sails

two sets part new

Anchors, No. of

25 lb. 1 lb. 1 lb. 1 lb.

Cables

180 fath. 30 fath. 30 fath. 30 fath.

Hawsers and Warps

7 lb. 6 lb. 3 lb. 3 lb.

Standing and Running Rigging

good

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

not required found good

Scraped the Bottom, and coated with Coal tar & asphaltum boiled two coats, with Green Paint on Topsides & gether painted &c. and last day, scraped all the inside plating as informed and is painted down to Copper at bilges, and am of opinion she may be continued as classed A.S. being in a state of complete repair and efficiency

Committee's Minute

23rd. July.

1878

Character assigned

A

George Wright Surveyor & Lloyd's Register & Certificate (if required).

TBW

No.

Survey held at

Date

18

on the

Master

Tonnage

Built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port of

Classed

The present Condition of the

Decks

Treenails

Windlass and Capstan

Waterways

Breasthooks and Stemson

Pumps

Comings

Transoms, Pointers, and Crutches

Boats

Upper Deck Beams & Fastenings

Timbers of the Frame at the Openings

Masts, Yards, &c.

Lower Deck Beams & Fastenings

Ditto ditto at other places

Sails

Planksheers

Keelsons

Anchors, No. of

Sheerstrakes

Clamps and Shelves

Cables

Topsides

Ceiling

Hawsers and Warps

Wales

Rudder

Standing and Running Rigging

Plank (Bottom) and Counter

Copper When put on

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute

18

Character assigned



© 2019

Certificate (if required).

1202479-0247

Lloyd's Register Foundation