

ANNUAL SURVEYS.

21432 37.360

No. in Reg. Book. on the Ship "Otaki" Survey held at London Date, first Survey 11th July Last Survey 13th July 1878
322 Tonnage 1014 Built at Newcastle When built 1875 8th mo.
 By whom built Palmer's Owners New Zeal. Shipp. Comp^y
 Port belonging to London Destined Voyage _____
 If Surveyed ~~Afloat~~ or in Dry Dock Canal Dry Dock

Last Survey, No. 20664 Port of Iron Classed _____ Years assigned _____ Character in Register Book. 100 A1
 Present Condition of the Decks Good Iron Good where seen
 Waterways _____ Breasthooks and Stemson do
 Comings _____ Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings _____ ~~Timbers of the Frame~~ at the Openings do
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places do
 Planksheers _____ Keelsons do
 Sheerstrakes _____ Clamps and Shells _____
 Topsides Plating _____ Ceiling do
 Wales _____ Rudder good
~~Plank~~ (Bottom) and Counter _____ Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers good Cargo and Main Hatchways good Hatches _____
 General Observations, Opinion as to Class, &c. _____

Rudder braces rebushed & Bottom cleaned & repainted.
 Surveyed with Ballast on board.
 She is now in good, efficient condition & eligible in our opinion to remain as classed.

Committee's Minute _____ 23rd. July, 1878. _____
 Character assigned 100 A1 _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. on the Ship "Brilliant" Survey held at London Date, first Survey 12th July Last Survey 12th July 1878
704 Tonnage 1613 Built at Aberdeen When built 1877 7th mo.
 By whom built Duthie Owners J. Duthie Sons & Co.
 Port belonging to Aberdeen Destined Voyage _____
 If Surveyed ~~Afloat~~ or in Dry Dock Green's Upper Dry Dock

Last Survey, No. 19019 Port of Iron Classed _____ Years assigned _____ Character in Register Book. 100 A1
 Present Condition of the Decks Good Iron Good where seen
 Waterways _____ Breasthooks and Stemson do
 Comings _____ Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings _____ ~~Timbers of the Frame~~ at the Openings do
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places do
 Planksheers _____ Keelsons do
 Sheerstrakes _____ Clamps and Shells _____
 Topsides Plating _____ Ceiling do
 Wales _____ Rudder good
~~Plank~~ (Bottom) and Counter _____ Copper or Y.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers good Cargo and Main Hatchways good Hatches _____
 General Observations, Opinion as to Class, &c. _____

Bottom cleaned & repainted.
 Surveyed with Ballast on board.
 She is now in good, efficient condition & eligible in our opinion to remain as classed.

Committee's Minute _____ 23rd. July, 1878. _____
 Character assigned 100 A1 _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____