

ANNUAL SURVEYS.

21231

Recd 10/7/78

No. in Reg. Book *13* on the *S. S. Verissa* Survey held at *Swansea* Date, first Survey *8* Last Survey *26 June* 1878
 Tonnage *1299* Built at *Newcastle* When built *1877-9th mo*
 By whom built *Palmer* Owners *J. Fenwick & Son*
 Port belonging to *London* Destined Voyage *Cardiff*
 If Surveyed ~~Afloat on~~ in Dry Dock *Globe dry dock*

Last Survey, No. *19636* Port of *Iron* Classified *100 A 1*

Present Condition of the Decks	<i>good</i>	Timbers <i>Rivets</i>	<i>good</i>
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"
Planksheers	"	Keelsons	"
Sheerstrakes	"	Clamps and Shelves	"
Topsides	"	Ceiling	"
Wales	"	Rudder	"
Plank (Bottom) and Counter	"	Copper or V.M. <i>Paint</i> When put on <i>Now</i>	
Engine Room Skylights	<i>good</i>	Caulking of Bottom, Deck, & Waterways	<i>good</i>
Coal Bunker, Openings, Lids, &c.	<i>good</i>	Scuppers	"
General Observations, Opinion as to Class, &c.	<i>This Vessel has now been cleaned and painted is in good condition and in my opinion eligible to remain as Classed.</i>		

Windlass and Capstan *good*
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained *Exam^d*
 Sails *Suit & spare* "
 Anchors, No. of *Complete* "
 Cables *not raised* "
 Hawseers and Warps *sufficient* "
 Standing and Running Rigging "

Committee's Minute *12th July, 1878.*
 Character assigned *100 A 1*

Thos. Ashton
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) *24* Paid *2 July* 1878

120N479-0282

