

ANNUAL SURVEYS.

No. 21450 Survey held at London Date, first Survey 27 July 1878 Last Survey 31 July 1878
 No. in on the 13th River Boyne Master Rice
 Book. 6 Tonnage 499 Built at Glasgow When built 1867 1st ms.
 By whom built Dobie Owners J. Hargrove
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock King and Queen Dry Dock

Last Survey, No. 16786 Port of Liver Classed S.S. L. No 2-75-776
 Present Condition of the Decks Good Rivets Good
 Waterways do Breasthooks and Stemson Good
 Comings do Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings do Ditto ditto at other places where
 Planksheers do Keelsons Good
 Sheerstrakes do Clamps and Shelves Good
 Topsides do Ceiling seen
 Wales do Rudder Good
 Plating do Copper or Y.M. Paint When put on now
 Plank (Bottom) and Counter do Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers do Cargo and Main Hatchways do Hatches do

General Observations, Opinion as to Class, &c.
Vessel placed in dry dock - bottom scraped and painted, rudder lifted and pintles bushed.
She now appears to be in a good and efficient condition and is eligible in my opinion to remain as classed.

Committee's Minute 14th August 1878
 Character assigned * A 1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 21450 Survey held at London Date, first Survey 27th July Last Survey 30th July 1878
 No. in on the Ship "Weathersfield" Master Sherris
 Reg. Book. 168 Tonnage 1051 Built at Pt. Glasgow When built 1865 2nd ms.
 By whom built Duncan Owners Greenfields, Cowie & Co.
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock West Ind. Dry Dock

Last Survey, No. 18841 Port of Liver Classed S.S. L. No 3-77
 Present Condition of the Decks Good Rivets Good where seen
 Waterways " Breasthooks and Stemson do do
 Comings " Transoms, Pointers, and Crutches do do
 Upper Deck Beams & Fastenings " ~~Timbers~~ of the Frame at the Openings do do
 Lower Deck Beams & Fastenings " Ditto ditto at other places do do
 Planksheers " Keelsons do do
 Sheerstrakes " Clamps and Shelves do do
 Topsides Plating " Ceiling do do
 Wales " Rudder good
 Plank (Bottom) and Counter " Copper or Y.M. Paint When put on now
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches "

General Observations, Opinion as to Class, &c.
Bottom cleaned & painted. Surveyed with ballast in hold.
She is now in good efficient condition & eligible in my opinion to remain as classed.

Committee's Minute 14th August 1878
 Character assigned * A 1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18