

# ANNUAL SURVEYS.

No.            Survey held at London Date, first Survey July 21 Last Survey July 25<sup>th</sup> 1878  
 No. in on the SS Sabrina Master Johnson  
 Reg. Book. 10 Tonnage 638 Built at Newcastle When built 1865 6M  
 By whom built Palmer Owners London Steam Ship Co  
 Port belonging to London Destined Voyage             
 If Surveyed Afloat or in Dry Dock Pontoon

Last Survey, No. 18822 Port of Iron Classed C / 6.77  
 Present Condition of the Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Lead When put on new  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom scraped & leaded

*She is now in good condition and entitled to remain as classed.*

Committee's Minute 9<sup>th</sup> August 1878

Character assigned A 1

*Leahouse Martindale*

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)            Paid            1878

No.            Survey held at London Date, first Survey July 21 Last Survey July 25 1878  
 No. in on the SS Thornbrough Master J Coleman  
 Reg. Book. 242 Tonnage 463 Built at Newcastle When built 1874 8M  
 By whom built Palmer Owners J Fenwick & Son  
 Port belonging to London Destined Voyage             
 If Surveyed Afloat or in Dry Dock Pontoon

Last Survey, No. 20651 Port of Iron Classed 90 A 1 - 2-78  
 Present Condition of the Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Lead When put on             
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom scraped & leaded

*She is now in good condition and entitled to remain as classed.*

Committee's Minute 9<sup>th</sup> August 1878

Character assigned 90 A 1

*Leahouse Martindale*

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)            Paid            1878