

ANNUAL SURVEYS.

21534-37625

No. _____ Survey held at London Date, first Survey Aug 8th Last Survey Aug 15th 1878
 No. in on the SS Statura Master _____
 Reg. Book. 1086 Tonnage 733 Built at Newcastle When built 1868 4M
 By whom ^{built} Palmer Owners London Steamship Co.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Pontoon

Years assigned. 100A/10.77
 Character in Register Book. SS Lon M 2-77
 Classed _____

Last Survey, No. 19544 Port of London
 Present Condition of the
 Decks now caulked. Good Treenails Rivets Good
 Waterways _____ " Breasthooks and Stenson _____ "
 Comings _____ " Transoms, Pointers, and Crutches _____ "
 Upper Deck Beams & Fastenings _____ " Timbers of the Frame at the Openings _____ "
 Lower Deck Beams & Fastenings _____ " Ditto ditto at other places _____ "
 Planksheers _____ " Keelsons _____ "
 Sheerstrakes _____ " Ceiling _____ "
 Topsides _____ " Rudder _____ "
 Wales _____ " Copper or Y.M. Coated When put on now
 Plank (Bottom) and Counter _____ " Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom scraped and coated & deck caulked.

Windlass and Capstan _____
 Pumps _____
 Boats _____
 Masts, Yards, &c. Good &
 Condition, how ascertained Sufficient -
 Sails _____ where
 Anchors, No. of 3 Bro. S.V. Ropes they
 Cables _____ could
 Hawseers and Warps _____ be seen
 Standing and Running Rigging _____

She is now in good condition and entitled to remain as classed.

Committee's Minute _____ 20th. August, 1878.
 Character assigned 100A/1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18
 Foundation

9140-632021

