

ANNUAL SURVEYS.

No. 120 Survey held at London Date, first Survey 1st Aug⁵ Last Survey 10th Aug 1878
 No. in on the BK "Verulam" Master E. Evans
 Reg. Book. 120 Tonnage 334 Built at Greenock When built 1876 - 2 mo
 By whom built J. E. Scott Owners Bullard, King & Co
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Nelson St Patent Slip

Last Survey, No. 19382 Port of Iron Classed 100 A.1
 Present Condition of the
 Decks how caulked Good Treenails Rivets Good
 Waterways Good Breasthooks and Stemson do
 Comings Good Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings Good Ditto ditto at other places do
 Planksheers Good Keelsons do
 Sheerstrakes Good Clamps and Shelves do
 Topsides Good Ceiling do
 Wales Good Rudder do
 Plates Good Copper or Y.M. When put on
 Plank (Bottom) and Counter Good Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom cleaned and coated with Gays paint
She is now in a good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 20th. August, 1878. Geo J. Rickard
 Character assigned 100 A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1878

No. 542 Survey held at London Date, first Survey 7th Aug Last Survey 9th Aug 1878
 No. in on the BK Martha Jackson Master Conner
 Reg. Book. 542 Tonnage 502 Built at Sunderland When built 1863 - 4 mo
 By whom built Laing Owners J Hargrove
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Bull Head Dry Dock

Last Survey, No. 18306 Port of Iron Classed A.1
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plates do Copper or Y.M. When put on
 Plank (Bottom) and Counter do Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Vessel surveyed with ballast in hold, where
seen she is in a good and efficient condition and eligible in my
opinion to remain as classed.
Paints brushed with white metal.

Committee's Minute 20th. August, 1878. Geo J. Rickard
 Character assigned A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1878