

ANNUAL SURVEYS.

No. 324 Survey held at London Date, first Survey 20th August Last Survey 21st August 1878
 No. in on the Ship "Carra dale" Master J. Mc Dermitt
 Reg. Book. 324 Tonnage 1242 Built at Glasgow When built 1877 4th mo.
 By whom built Dobie Owners S. Manford
 Port belonging to Glasgow Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Canal Dry Dock

Last Survey, No. 18461 Port of London Classed _____ Years assigned. _____ Character in Register Book. 100 A1
 Present Condition of the Decks Good Freenails Rivets Good where seen
 Waterways _____ Breasthooks and Stemson _____ do
 Comings _____ Transoms, Pointers, and Crutches _____ do
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ do
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ do
 Planksheers _____ Keelsons _____ do
 Sheerstrakes _____ Clamps and Shelves _____ do
 Topsides Plating _____ Rudder good _____ do
 Wales _____ Copper or F.M. Paint When put on now _____ do
 Plank (Bottom) and Counter _____ Caulking of Bottom, Deck, & Waterways good _____ do
 Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers do Cargo and Main Hatchways good Hatches _____ do
 General Observations, Opinion as to Class, &c. _____

Bottom cleaned & repainted
Surveyed with part outward cargo in holds.

She is now in good, efficient condition & eligible in my opinion to remain as classed.

Committee's Minute 30th August, 1878. H. Paulsen.
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at London Date, first Survey 22nd August Last Survey 23rd August 1878
 No. in on the Bk. "Selim" Master J. Dick
 Reg. Book. 517 Tonnage 723 Built at Sunderland When built 1869 7th mo.
 By whom built Sliff Owners J. A. Simpson
 Port belonging to Leith Destined Voyage _____
 If Surveyed Afloat or in Dry Dock West Ind. Dry Dock

Last Survey, No. 18609 Port of London Classed _____ Years assigned. _____ Character in Register Book. * A1
 Present Condition of the Decks Good Freenails Rivets Good where seen
 Waterways _____ Breasthooks and Stemson _____ do
 Comings _____ Transoms, Pointers, and Crutches _____ do
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ do
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ do
 Planksheers _____ Keelsons _____ do
 Sheerstrakes _____ Clamps and Shelves _____ do
 Topsides Plating _____ Rudder good _____ do
 Wales _____ Copper or F.M. Paint When put on now _____ do
 Plank (Bottom) and Counter _____ Caulking of Bottom, Deck, & Waterways good _____ do
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers do Cargo and Main Hatchways good Hatches _____ do
 General Observations, Opinion as to Class, &c. _____

Bottom cleaned & repainted. Rudder braces rebushed.
Surveyed with ballast in hold.

She is now in good, efficient condition & eligible in my opinion to remain as classed.

Committee's Minute 30th August, 1878. H. Paulsen.
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____