

ANNUAL SURVEYS.

No. 4512 Survey held at Greenock Date, first Survey 8th Aug^r Last Survey 2/9/78 1878
 No. in on the gun Bk "Clwy" Master Williams
 Reg. Book 776 Tonnage 769 Built at Liverpool When built 1876 11 mo
 By whom built Royden Owners O. Jones & Co
 Port belonging to Liverpool Destined Voyage Rangoon
 If Surveyed Afloat or in Dry Dock East Dry Dock

Last Survey, No. 20197 Port of Batavia Iron Classed 100 A1
 Present Condition of the Good where seen Years assigned. 10-77 Character in Register Book.
 Decks Good where seen Ribs Good where seen
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Rudder "
 Copper or Y.M. ✓ When put on ✓
 Caulking of Bottom, Deck, & Waterways Good where seen
 Windlass and Capstan Good
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained By observation
 Sails Well found
 Anchors, No. of 3 B. 1 S. 2 K
 Cables Good
 Hawser and Warps "
 Standing and Running Rigging "
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Hold not cleared, some Cargo of Coals amidsthips for ballast. Bottom scraped & coated with Paint.
I am of opinion this Vessel is eligible to remain as
Classed.

Committee's Minute 3rd September, 1878. H. J. 800014
 Character assigned 100 A1 GP Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1878

No. 4512 Survey held at Greenock Date, first Survey 22nd Aug^r Last Survey ✓ 1878
 No. in on the gun S. S. "Blenheim" Master Ball
 Reg. Book 721 Tonnage 735 Built at Hartlepool When built 1877 10 mo
 By whom built Withy Owners Steel Young & Co
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Harvel Dry Dock

Last Survey, No. 20197 Port of Hartlepool Iron Classed 90 A1
 Condition of the Good where seen Years assigned. 11-77 Character in Register Book.
 Decks Good where seen Ribs Good where seen
 Waterways " Breasthooks and Stenson not spanned
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings not seen Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers Good where seen Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Rudder Good where seen
 Copper or Y.M. ✓ When put on ✓
 Caulking of Bottom, Deck, & Waterways Good where seen
 Windlass and Capstan Good where seen
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained By observation
 Sails Well found
 Anchors, No. of Good where seen
 Cables "
 Hawser and Warps "
 Standing and Running Rigging "
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom scraped and coated with Paint.

I am of opinion this Vessel is eligible to remain
as Classed.
 Committee's Minute 3rd September, 1878. H. J. 20197
 Character assigned 90 A1 GP Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1878