

ANNUAL SURVEYS.

No. Survey held at London Date, first Survey Aug 22^d Last Survey Aug 26 1878
 No. in on the S Montgomeryshire Master Nelson
 Reg. Book. 1260 Tonnage 1401 Built at Liverpool When built 1877 64
 By whom built Royan Owners Hughes & Co
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Pentoon Ballast in.
 Last Survey, No. 18893 Port of Iron Iron Classed 100 A. 7. 77

Present Condition of the
 Decks good Treenails Rivets good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Bottom When put on new
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Bottom bottom.

She is now in good condition and entitled to remain as Clapnet

Committee's Minute 30th August, 1878.
 Character assigned 100 A

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at London Date, first Survey Aug 13 Last Survey Aug 16 1878
 No. in on the BR Ben Macdonald Master J M Millan
 Reg. Book. 266 Tonnage 1100 Built at Glasgow When built 1877 34
 By whom built Burday Owners Watson Br.
 Port belonging to Glasgow Destined Voyage
 If Surveyed Afloat or in Dry Dock by BR Part cargo in
 Last Survey, No. 18357 Port of Iron Classed 100 A 1

Present Condition of the
 Decks good Treenails Rivets good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Bottom When put on new
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Bottom bottom.

She is now in good condition and entitled to remain as Clapnet

Committee's Minute 30th August, 1878.
 Character assigned 100 A

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18