

# ANNUAL SURVEYS.

No. 473 Survey held at London Date, first Survey 30th August Last Survey 31st August 1878  
 No. in on the Ship "Pleiades" Master H. Setten  
 Reg. Book. 473 Tonnage 997 Built at Dumbarton When built 1869 9th mo.  
 By whom built M. Millan Owners Shaw, Savill & Co.  
 Port belonging to Southampton Destined Voyage   
 If Surveyed Afloat or in Dry Dock Commercial Dry Dock

Last Survey, No. 19749 Port of Lion.

Classed  Years assigned.  Character in Register Book. \*A1  
11.77

Waterways	Good	Transoms	Rivets	Good where seen	
Comings	"	Breasthooks and Stems		do	
Upper Deck Beams & Fastenings	"	Transoms, Pointers, and Grutches		do	
Lower Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		do	
Planksheers	"	Ditto ditto at other places		do	
Sheerstrakes	"	Keelsons		do	
Topsides	Plating	Clamps and Shells		do	
Wales	"	Ceiling		do	
Plank (Bottom) and Counter	"	Rudder	good		
Engine Room Skylights	"	Copper or F.M. Paint	When put on	now	
Coal Bunker, Openings, Lids, &c.	"	Caulking of			
General Observations, Opinion as to Class, &c.	"	Bottom, Deck, & Waterways	good		
		Scuppers	"		
		Cargo and Main Hatchways	good		
		Hatches	"		

Bottom cleaned & repainted.

Rudder braces rebushed.

Surveyed with ballast in hold.

She is now in good condition & eligible in my opinion to remain as classed.

Committee's Minute 10th September, 1878.

Character assigned

H. Paulsen  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)  Paid  18

No.  Survey held at London Date, first Survey 30th August Last Survey 30th August 1878  
 No. in on the Ship "County of Carnarvon" Master R. Roberts  
 Reg. Book. 1384 Tonnage 1470 Built at Liverpool When built 1877 1st mo.  
 By whom built Evans Owners H. Thomas & Co.  
 Port belonging to Liverpool Destined Voyage   
 If Surveyed Afloat or in Dry Dock of Walker & Co. Deptford.

Last Survey, No. 17938 Port of Lion

Classed  Years assigned.  Character in Register Book. 100 A1  
3.77

Decks	Good	Transoms	Rivets	Good where seen	
Waterways	"	Breasthooks and Stems		do	
Comings	"	Transoms, Pointers, and Grutches		do	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		do	
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		do	
Planksheers	"	Keelsons		do	
Sheerstrakes	"	Clamps and Shells		do	
Topsides	Plating	Ceiling		do	
Wales	"	Rudder	good		
Plank (Bottom) and Counter	"	Copper or F.M. Paint	When put on	now	
Engine Room Skylights	"	Caulking of			
Coal Bunkers, Openings, Lids, &c.	"	Bottom, Deck, & Waterways	good		
General Observations, Opinion as to Class, &c.	"	Scuppers	"		
		Cargo and Main Hatchways	good		
		Hatches	"		

Bottom cleaned & repainted.

Surveyed with ballast in hold.

He is now in good condition & eligible in my opinion to remain as classed.

Committee's Minute 10th September, 1878.

Character assigned

H. Paulsen  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)  Paid  18