

ANNUAL SURVEYS.

No. 26196 Survey held at Liverpool Date Aug 28th 1878.
 on the Ship "Golden Gate" Master Nempe
 Tonnage 899 Built at Liverpool When built 1869 - 7 mo.
 By whom built Royden Owners Cotesworth Lyne & Co.
 Port belonging to Liverpool Destined Voyage San Francisco.
 If Surveyed Afloat or in Dry Dock Princes Dry Dock

Last Survey, No. X^{*} 19236 Port of Iron Classed *A1
 S.S. Liv No 2-77. 10.77.

The present Condition of the	Good	Timber Rivets.	Good.	Windlass and Capstan	Good.
Decks					
Waterways	✓	Breasthooks and Stemson	✓	Pumps	✓
Comings	✓	Transoms, Pointers, and Crutches	✓	Boats	✓
Upper Deck Beams & Fastenings	✓	Timbers of the Frame at the Openings	✓	Masts, Yards, &c.	✓
Lower Deck Beams & Fastenings	✓	Ditto ditto at other places	✓	Sails	✓
Planksheers	✓	Keelsons	✓	Anchors, No. of <u>3B-15-2K</u>	
Sheerstrakes	✓	Clamps and Shells		Cables <u>part seen</u>	Good
Topsides	✓	Ceiling	✓	Hawsers and Warps	and
Wales	✓	Rudder	✓	Standing and Running Rigging	Sufficient
Plank (Bottom) and Counter	✓	Copper Cement When put on <u>69</u>			

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good.

Bottom sighted, cleaned and coated with paint, and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool Sept 17 1878

Character assigned *A1 RS T. Shilston.
 Certificate (if required).

No. Survey held at Liverpool Date Sep 7th 1878.
 on the Bark "Geta" Master Collins.
 Tonnage 696 Built at Glasgow When built 1865 - 8 mo.
 By whom built Stephen Owners Urmeneta & Co
 Port belonging to Valparaiso. Destined Voyage So. America.
 If Surveyed Afloat or in Dry Dock Clarence Dry Dock

Last Survey, No. 19372 Port of Iron Classed *A1
 S.S. Liv No 3-77. 9.77.

The present Condition of the	Good	Timber Rivets.	Good.	Windlass and Capstan	Good.
Decks					
Waterways	✓	Breasthooks and Stemson	✓	Pumps	✓
Comings	✓	Transoms, Pointers, and Crutches	✓	Boats	✓
Upper Deck Beams & Fastenings	✓	Timbers of the Frame at the Openings	✓	Masts, Yards, &c.	✓
Lower Deck Beams & Fastenings	✓	Ditto ditto at other places	✓	Sails	✓
Planksheers	✓	Keelsons	✓	Anchors, No. of <u>3B-15-2K</u>	
Sheerstrakes	✓	Clamps and Shells		Cables <u>part seen</u>	Good
Topsides	✓	Ceiling	✓	Hawsers and Warps	and
Wales	✓	Rudder	✓	Standing and Running Rigging	Sufficient
Plank (Bottom) and Counter	✓	Copper Cement When put on <u>65/pt 74</u>			

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good.

Bottom sighted, cleaned and coated with paint and the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool Sep 17 1878

Character assigned *A1 RS T. Shilston.
 Certificate (if required).

'Golden Gate'
'Geta'
26/96



© 2019

Lloyd's Register
Foundation