

# ANNUAL SURVEYS.

Rec'd 19. 9. 76

No. in Reg. Book. on the **1499** No. **1499** Survey held at **London** Date, first Survey **30 July** Last Survey **8 August 1878**  
 Tonnage **465** Built at **Oundle** Master **—**  
 By whom built **Hayes** Owners **General Ste Navig Co**  
 Port belonging to **London** Destined Voyage **—**  
 If Surveyed Afloat or in Dry Dock **Dry Dock Deptford Green**

Last Survey, No. **17101** Port of **London** Classed **90 A 1**  
 Present Condition of the Decks **Good** **Good** **Good**  
 Waterways **do** Breasthooks and Stenson **do** Windlass and Capstan **Good**  
 Comings **do** Transoms, Pointers, and Crutches **do** Pumps **do**  
 Upper Deck Beams & Fastenings **do** Timbers of the Frame at the Openings **do** Boats **do**  
 Lower Deck Beams & Fastenings **do** Ditto ditto at other places **do** Masts, Yards, &c. **do**  
 Planksheers **do** Keelsons **do** Condition, how ascertained **from deck**  
 Sheerstrakes **do** Clamps and Shelves **do** Sails **well found**  
 Topsides **do** Ceiling **do** Anchors, No. of **3 B. 1 S & Kedges**  
 Wales **do** Rudder **do** Cables **complete**  
 Plank (Bottom) and Counter **do** Copper or Y.M. **—** When put on **—** Hawser and Warps **sufficient**  
 Engine Room Skylights **Good** Caulking of Bottom, Deck, & Waterways **Good** Standing and Running Rigging **Good**  
 Coal Bunker, Openings, Lids, &c. **Good** Scuppers **Good** Cargo and Main Hatchways **Good** Hatches **Good**  
 General Observations, Opinion as to Class, &c. **—**

**Bottom cleaned and recoated. Rudder repaired. This vessel appears in good condition and eligible to remain as classed.**

Committee's Minute **24th September, 1878.** Character assigned **90 A 1**  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **—** Paid **—** 18 **—**

No. in Reg. Book. on the **112** No. **112** Survey held at **London** Date, first Survey **3 Sep** Last Survey **5th Sept 1878**  
 Tonnage **1319** Built at **Liverpool** Master **A. Burns**  
 By whom built **Vernon** Owners **L. Young & Co**  
 Port belonging to **Liverpool** Destined Voyage **—**  
 If Surveyed Afloat or in Dry Dock **L.W. D. Dry Dock**

Last Survey, No. **18958** Port of **Liverpool** Classed **A 1**  
 Present Condition of the Decks **good** **good** **good**  
 Waterways **do** Breasthooks and Stenson **do** Windlass and Capstan **good**  
 Comings **do** Transoms, Pointers, and Crutches **do** Pumps **2**  
 Upper Deck Beams & Fastenings **do** Timbers of the Frame at the Openings **do** Boats **4**  
 Lower Deck Beams & Fastenings **do** Ditto ditto at other places **not seen** Masts, Yards, &c. **do**  
 Planksheers **do** Keelsons **good where seen** Condition, how ascertained **from deck & enquiry**  
 Sheerstrakes **Plating** **do** Ceiling **do** Sails **well found**  
 Topsides **do** Rudder **good** Anchors, No. of **3 B, 1 S & 2 K**  
 Wales **do** Copper or Y.M. **—** When put on **—** Cables **complete**  
 Plank (Bottom) and Counter **do** Caulking of Bottom, Deck, & Waterways **good** Hawser and Warps **good & suff**  
 Engine Room Skylights **—** Coal Bunkers, Openings, Lids, &c. **—** Scuppers **do** Standing and Running Rigging **good**  
 Cargo and Main Hatchways **good** Hatches **do**

**Bottom cleaned and recoated. Rudder and found pintles in good condition. Hold examined with Ballast therein. The vessel appears in good condition and is, in my opinion, eligible to remain as classed.**

Committee's Minute **24th September, 1878.** Character assigned **A 1**  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) **—** Paid **—** 18 **—**