

ANNUAL SURVEYS.

No. Survey held at London Date, first Survey Sept 13 Last Survey Sept 13 1878
 No. in on the SS Oakdale Master J. Alderson
 Reg. Book. 7 Tonnage 857 Built at Leamthorpe When built 1878-3M
 By whom built Wm. H. H. H. Owners Steel Young & Co.
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 20857 Port of Iron Classed 100A-478
 Present Condition of the
 Decks Good Treennails Pine Good
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. Coated When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom scraped & coated

She is now in good condition and entitled to remain as classed. A few Butts in the bottom have been caulked, every to being in the present

Committee's Minute 24th September, 1878.

Character assigned 100A

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at London Date, first Survey Sept 5 Last Survey Sept 5 1878
 No. in on the SS City of Mecca Master Marr
 Reg. Book. 850 Tonnage 1461 Built at Glasgow When built 1871-3M
 By whom built Cornell Owners J. Smith & Sons
 Port belonging to Glasgow Destined Voyage
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 19424 Port of Iron Classed 100A-577
 Present Condition of the
 Decks Good Treennails Pine Good
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. Coated When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom scraped & coated

She is now in good condition and entitled to remain as classed. The Chain Cables were now hauled on deck for the Board of Trade Surveyors I have surveyed them and found them good & complete

Committee's Minute 24th September, 1878.

Character assigned 100A

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18