

ANNUAL SURVEYS.

No. 1354 Survey held at London Date, first Survey 3 Sept 1878 Last Survey 5 Sept 1878
 No. in on the Assey Master Hunter Robinson
 Reg. Book. 1354 Tonnage 795 Built at Glasgow When built 1876 - 12 mo
 By whom built Low & Glas. Co Owners D Hunter
 Port belonging to Assey Destined Voyage
 If Surveyed Afloat or in Dry Dock Bull Head Dry Dock

Last Survey, No. 17604 Port of Iron Classed 100A 1
 Present Condition of the Decks Good Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places where
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wyes Good Rudder Good
 Plating (Bottom) and Counter Good Copper or V.M. Paint When put on Good
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

She is now in a good and efficient condition and is eligible in my opinion to remain as classed

Committee's Minute 27th September, 1878
 Character assigned 100A 1

J. Hearle
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 40 Survey held at London Date, first Survey 11 Sept 1878 Last Survey 13 Sept 1878
 No. in on the S.S. Rainbow Master J. Minshell
 Reg. Book. 40 Tonnage 638 Built at Dundee When built 1871 10 mo.
 By whom built Gourlay Owners General Steam Navigation Co
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Deptford Green Gridiron & Afloat

Last Survey, No. 20294 Port of Iron Classed 100A 1
 Present Condition of the Decks good good
 Waterways good Breasthooks and Stemson good
 Comings good Transoms, Pointers, and Crutches good
 Upper Deck Beams & Fastenings good Timbers of the Frame at the Openings good
 Lower Deck Beams & Fastenings good Ditto ditto at other places good
 Planksheers good Keelsons good
 Sheerstrakes good Clamps and Shelves good
 Topsides good Ceiling good
 Wyes good Rudder good
 Plating (Bottom) and Counter good Copper or V.M. Paint When put on good
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c.

This vessel is now in a good and efficient condition and is eligible in my opinion to remain as classed.

Committee's Minute 27th September, 1878
 Character assigned 100A 1

J. Stanbury
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18