

REPORT of SURVEY for REPAIRS, &c.

No.

No. in
Reg. Book.

Survey held at

London

Date, first Survey Aug 14

Last Survey

Sept

1878

328 on the

S Persian Empire

Master

J Watson

TONNAGE under Tonnage Deck

1457

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

1532

Crew Space, as per Rule

Register Tonnage, cut on Beam

1532

Engine Room

Reg. Tons as St' mer, cut on Bm.

Built at

W Hartthorp

When built

1865

Owners

J Duncan

Port belonging to

London

Residence

By whom built

Pile

Destined Voyage

If Surveyed Afloat or in Dry Dock

Pontoon

Length of Poop House

ft. Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

19094

Port

London

Classed

A 8.77

SS No 2.74

REPAIRS, OR EXAMINATION AS PER RULE

SS No 3.

At the present time the vessel placed on the Pontoon. The hold cleared, and the close ceiling taken up in the bottom and bilges, (open ceiling above with) exposing both surfaces of plating, examined and found in good condition, cement tested which was adhering firmly to the iron.

Oxidation beaten or cut off laying bare the surface of iron. The plating was so good that there did not appear any necessity to bore them.

She has a gutter funnel & in Ward Waterway or Plank sheen. Ship loaded and painted & much of bedding renewed Patch Pine

one New Plate in Bilge & 2 additional Angle Iron in the inside

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Plank sheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Treenails

Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Good & Sufficient where they could be seen

She is now in good condition and entitled to remain as classed and Marked SS No 3-1878 in the Register Book.

Leahouse Martindale

The Amount of Entry Fee

£

received by me,

Special

£ 6 : 6 : -

22 Oct 1878

Certificate (if required)

£ - : 5 : -

(Travelling Expenses, if any, £)

Committee's Minute

1st October,

1878

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

480-0264