

ANNUAL SURVEYS.

No. in Reg. Book. 1052 Tonnage 555 Survey held at London Date, first Survey Aug 30 Last Survey Sept 28 1878
 on the S Star of Scotia Master Thompson
 Built at Belfast When built 1864 1 M
 By whom built Harland Owners J Barry & Co
 Port belonging to Belfast Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 19543 Port of Iron Classed _____ Years assigned _____ Character in Register Book S. S N° 3-77
 Present Condition of the
 Decks good Treenails Rivets good
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. bottom When put on non
 Caulking of _____
 Bottom, Deck, & Waterways good
 Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Bottom Scraped & bottomed

She is now in good condition and entitled to remain as classed.

Senhouse Martinvale

Committee's Minute 27th September, 1878.
 Character assigned DBW
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. 488 Survey held at London Date, first Survey Aug 24 Last Survey Apr 14 1878
 on the S Marlborough Master Anson
 Tonnage 1124 Built at O Glasgow When built 1876 6 M.
 By whom built Guncar Owners J Galbraith
 Port belonging to Glasgow Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 19053 Port of Iron Classed 100A-277 Years assigned _____ Character in Register Book _____
 Present Condition of the
 Decks good Treenails Rivets good
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. bottomed When put on non
 Caulking of _____
 Bottom, Deck, & Waterways good
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Bottom Scraped & bottomed

She is now in good condition and entitled to remain as classed.

Senhouse Martinvale

Committee's Minute 27th September, 1878.
 Character assigned DBW
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____