

ANNUAL SURVEYS.

No. 14100 Survey held at North Shields Date, first Survey 7 Oct 78 Last Survey 9 Oct 78 18 78
 No. in on the Scw. "Avena" Master Otto Hellberg
 Reg. Book. 1513 Tonnage 459 Built at Sunderland When built 1873-9 mo.
 By whom built Davison Owners W. Thorburn.
 Port belonging to Udderalla Destined Voyage Udderalla
 If Surveyed Afloat or in Dry Dock In Smith's Dry Dock

Last Survey, No. 21059 Port of Iron Classed S.L. Lon No 1-78 Years assigned. 90A.1 Character in Register Book. 6.78
 Present Condition of the
 Decks good Treennails rivets good
 Waterways good Breasthooks and Stemson good
 Comings good Transoms, Pointers, and Crutches good
 Upper Deck Beams & Fastenings good Timbers of the Frame at the Openings good
 Lower Deck Beams & Fastenings good Ditto ditto at other places not seen
 Planksheers good Keelsons good
 Sheerstrakes good Clamps and Shelves good
 Topsides good Ceiling good
 Wales good Rudder good
 Plank (Bottom) and Counter good Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c.

A few rivets in the after part of the keel and in the lower part of the stern post replaced by new. The bottom has been painted. The vessel is in good and efficient condition and is eligible to remain as classed.
 Damage Survey / Splid / £1.1.0
 Oct 1878

Committee's Minute 22nd October, 18 78, J. H. Truworth.
 Character assigned 90A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18 78

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed Years assigned. Character in Register Book.
 Present Condition of the
 Decks Treennails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18