

ANNUAL SURVEYS.

No. 2194 Survey held at London Date, first Survey Oct 14 Last Survey Oct 14 1878
 No. in on the SS Elizabeth Martin Master J. P. P. P.
 Reg. Book. 462 Tonnage 809 Built at Glasgow When built 1872-5M
 By whom built Napier Owners A. Currie
 Port belonging to Greenock Destined Voyage
 If Surveyed Afloat or in Dry Dock By H

Last Survey, No. 2194 Port of Iron Classed 100A1 2-78
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom Scraped & coated

She is now in good condition and entitled to remain as classed

Senhouse Martinale

Committee's Minute 22nd October, 188.

Character assigned 100A1
TRW

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 16921 Survey held at London Date, first Survey Sept 17 Last Survey Oct 15 1878
 No. in on the S Harlinger Master
 Reg. Book. 87 Tonnage 1506 Built at Greenock When built 1876 SM
 By whom built Steele Owners Anderson Anderson & Co
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock By H

Last Survey, No. 16921 Port of Iron Classed 100A1 2-76
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom Scraped & coated

She is now in good condition and entitled to remain as classed

Senhouse Martinale

Committee's Minute 22nd October, 1878,

Character assigned 100A1
TRW

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18