

ANNUAL SURVEYS.

No. in Reg. Book. **No. 80** Survey held at **Amherst** Date, first Survey **21/10/78** Last Survey **27 Aug 1878**
 on the **Kate Tatham** Master **P. K. Kelly**
 Tonnage **275** Built at **Grimsby** When built **1863**
 By whom built **Stut** Owners **Leumie & Co**
 Port belonging to **Melbourne** Destined Voyage **London & Sydney**
 If Surveyed Afloat or in Dry Dock **in Patent slip & afloat**

Last Survey, No. **19488** Port of **Adelaide** Iron
 Present Condition of the
 Decks **in good condition** Treennails **Rivets in good order**
 Waterways **do do** Breasthooks and Stemson **do do**
 Comings **do do** Transoms, Pointers, and Crutches **do do**
 Upper Deck Beams & Fastenings **Secure** Timbers of the Frame at the Openings **good order**
 Lower Deck Beams & Fastenings **Single Deck** Ditto ditto at other places **do do**
 Planksheers **Plating in good order** Keelsons **in good order**
 Sheerstrakes **do do do** Clamps and Shelves **all in good order**
 Topsides **do do do** Ceiling **do do**
 Wales **do do do** Rudder **hangings in good order**
 Plank (Bottom) and Counter **Plating good** Copper or Y.M. **Paint** When put on **at date**
 Engine Room Skylights **Coal Bunker, Openings, Lids, &c.** Scuppers **good** Cargo and Main Hatchways **Secure** Hatches **Secure**
 General Observations, Opinion as to Class, &c. **I have examined this vessel in Patent slip & find all parts of the hull in good condition & free from corrosion & cement inside in good order & adhering firmly to the hull. The hull inside has been scraped & well coated with paint at date, and the rudder & hangings refitted. I am of opinion this vessel is well worthy of being continued in her present A 1 character as elapsed.**
 Committee's Minute **22nd October, 1878.**
 Character assigned **A 1**

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Ref. on 2. 41** Paid **Aug 1878**

No. **No.** Survey held at **Survey held at** Date, first Survey **Date, first Survey** Last Survey **Last Survey**
 on the **on the** Master **Master**
 Tonnage **Tonnage** Built at **Built at** When built **When built**
 By whom built **By whom built** Owners **Owners**
 Port belonging to **Port belonging to** Destined Voyage **Destined Voyage**
 If Surveyed Afloat or in Dry Dock **If Surveyed Afloat or in Dry Dock**

Last Survey, No. **Last Survey, No.** Port of **Port of** Classed **Classed**
 Present Condition of the
 Decks **Decks** Treennails **Treennails**
 Waterways **Waterways** Breasthooks and Stemson **Breasthooks and Stemson**
 Comings **Comings** Transoms, Pointers, and Crutches **Transoms, Pointers, and Crutches**
 Upper Deck Beams & Fastenings **Upper Deck Beams & Fastenings** Timbers of the Frame at the Openings **Timbers of the Frame at the Openings**
 Lower Deck Beams & Fastenings **Lower Deck Beams & Fastenings** Ditto ditto at other places **Ditto ditto at other places**
 Planksheers **Planksheers** Keelsons **Keelsons**
 Sheerstrakes **Sheerstrakes** Clamps and Shelves **Clamps and Shelves**
 Topsides **Topsides** Ceiling **Ceiling**
 Wales **Wales** Rudder **Rudder**
 Plank (Bottom) and Counter **Plank (Bottom) and Counter** Copper or Y.M. **Copper or Y.M.** When put on **When put on**
 Engine Room Skylights **Engine Room Skylights** Coal Bunkers, Openings, Lids, &c. **Coal Bunkers, Openings, Lids, &c.** Scuppers **Scuppers** Cargo and Main Hatchways **Cargo and Main Hatchways** Hatches **Hatches**
 General Observations, Opinion as to Class, &c. **General Observations, Opinion as to Class, &c.**

Committee's Minute **18**
 Character assigned **Character assigned**

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Certificate (if required)** Paid **Paid** 18 **18**