

No. in Reg. Book. on the **No. 2679** Survey held at **Swansea** Date, first Survey **(21968)** Last Survey **14th Oct** 18**78**
686 Tonnage **560** Built at **Glasgow** Master **J Rees**
By whom built **Stephen** When built **1875 7th mo**
Port belonging to **Swansea** Owners **J Tulloch & Co**
Destined Voyage **Valparaiso**
If Surveyed Afloat or in Dry Dock **20257**

Last Survey, No. **2603** Port of **Swansea Iron** Classified **100 A1**
Present Condition of the Decks **good** **Teennails** **Rivets** **good** **2.78**
Waterways **"** Breasthooks and Stenson **"**
Comings **"** Transoms, Pointers, and Crutches **"**
Upper Deck Beams & Fastenings **"** Timbers of the Frame at the Openings **"**
Lower Deck Beams & Fastenings **"** Ditto ditto at other places **"**
Planksheers **"** Keelsons **"**
Sheerstrakes **"** Clamps and Shelves **"**
Topsides **"** Ceiling **"**
Wales **"** Rudder **"**
Plank (Bottom) and Counter **"** Copper or F.M. Paint When put on **Now**
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers **"** Cargo and Main Hatchways **good** Hatches **"**
General Observations, Opinion as to Class, &c. **This Vessel has now been cleaned and Painted, is in good condition and in my opinion eligible to remain as classed.**
Windlass and Capstan **good**
Pumps **"**
Boats **"**
Masts, Yards, &c. **"**
Condition, how ascertained **exam^d**
Sails **Two Sails** **"**
Anchors, No. of complete **"**
Cables **not ranged** **"**
Hawsers and Warps **Sufficient** **"**
Standing and Running Rigging **"**

Committee's Minute

Character assigned

25th Oct 18**78**

100 A1

TRM

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) **No Paid Fee received**