

ANNUAL SURVEYS.

No. 40 Survey held at London Date, first Survey 25th Octr. Last Survey 25th Octr. 18 78
 No. in on the S. S. "Rainbow" Master Minshell
 Reg. Book. 40 Tonnage 638 Built at Dundee When built 1871 10th mo.
 By whom built Gourlay Owners Gen. St. Nav. Comp^y.
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock on G. St. Nav. Comp^y. Gridiron

Last Survey, No. 21765 Port of Iron Classified 100 A1
 Years assigned. 9.78 Character in Register Book.

Present Condition of the
 Decks Good Freenails Good where seen Rivets Good where seen
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shells do
 Topsides do Ceiling do
 Wales do Rudder good
 Plank (Bottom) and Counter do Copper or F.M. Paint When put on Sept. 78
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers do Cargo and Main Hatchways good Hatches do
 General Observations, Opinion as to Class, &c.

This vessel, having lately been aground for about 12 hours in the river Elbe, her keel and bottom has now been examined and found to be free from injury.
She is in good, efficient condition and in my opinion eligible to remain as classed.

Committee's Minute 5th November, 1878. H. Paulsen.
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) DBW Paid 18

No. 601 Survey held at London Date, first Survey 26th Octr. Last Survey 29th Octr. 18 78
 No. in on the Bk. "Rothsay Bay" Master J. Carmack
 Reg. Book. 601 Tonnage 750 Built at Dumbarton When built 1877 9th mo.
 By whom built Birrell Owners Hatfield, Cameron & Co.
 Port belonging to Glasgow Destined Voyage
 If Surveyed Afloat or in Dry Dock West India Dry Dock

Last Survey, No. 19527 Port of Iron Classified 100 A1
 Years assigned. 11.77 Character in Register Book.

Present Condition of the
 Decks Good Freenails Good where seen Rivets Good where seen
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shells do
 Topsides do Ceiling do
 Wales do Rudder good
 Plank (Bottom) and Counter do Copper or F.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights do Coal Bunkers, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways good Hatches do
 General Observations, Opinion as to Class, &c.

Bottom cleaned & repainted.
Surveyed with masts & dunnage wood in hold.
She is now in good, efficient condition & eligible in my opinion to remain as classed.

Committee's Minute 5th November, 1878. H. Paulsen.
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) DBW Paid 18