

ANNUAL SURVEYS.

No. 1033 Survey held at London Date, first Survey 14th Octbr. Last Survey 15th Octbr. 18 78.
 No. in on the Ship "Star of Erin" Master J. Coulter
 Reg. Book. 1033 Tonnage 949 Built at Belfast When built 1862 10th mo.
 By whom built Harland Owners J. Curry & Co.
 Port belonging to Belfast Destined Voyage
 If Surveyed ~~Afloat~~ in Dry Dock Canal Dry Dock

Last Survey, No. 19722 Port of Iron Classed 12.77
 Present Condition of the Decks Good Transoms Rivets Good where seen
 Waterways " Breasthooks and Stems do Windlass and Capstan Good
 Comings " Transoms, Pointers, and Crutches do Pumps "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings do Boats 4 in number
 Lower Deck Beams & Fastenings " Ditto ditto at other places do Masts, Yards, &c. "
 Planksheers " Keelsons do Condition, how ascertained from deck & enquiry
 Sheerstrakes " Clamps and Shells do Sails well found
 Topsides " Ceiling do Anchors, No. of 3 B. 1 St. 2 Keds.
 Wales " Rudder good Cables complete
 Plank (Bottom) and Counter " Copper or F.M. Paint When put on now Hawser and Warps "
 Caulking of Bottom, Deck, & Waterways good Standing and Running Rigging "
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers do Cargo and Main Hatchways good Hatches "

General Observations, Opinion as to Class, &c.
Bottom cleaned & painted. - Surveyed with cargo in hold. -
Called to owners attention that Sp. Survey No. 1 is ^{nearly} due, but the owners desire to
postpone the survey. -
She is now in good, efficient condition & eligible in our opinion to remain
as classed. -
 Committee's Minute 1st November, 1878.
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 604 Survey held at London Date, first Survey 22nd Octbr. Last Survey 22nd Octbr. 18 78
 No. in on the Ship "Lock Tyne" Master Martin
 Reg. Book. 604 Tonnage 1213 Built at Glasgow When built 1876 10th mo.
 By whom built Thomson Owners Gen. Shipp. Comp^y.
 Port belonging to Glasgow Destined Voyage
 If Surveyed ~~Afloat~~ in Dry Dock of Messrs. Walker, Deptford Green

Last Survey, No. 19853 Port of Iron Classed 100 A1
 Present Condition of the Decks Good Transoms Rivets Good where seen
 Waterways " Breasthooks and Stems do Windlass and Capstan Good
 Comings " Transoms, Pointers, and Crutches do Pumps "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings do Boats 4 in number
 Lower Deck Beams & Fastenings " Ditto ditto at other places do Masts, Yards, &c. "
 Planksheers " Keelsons do Condition, how ascertained from deck & enquiry
 Sheerstrakes " Clamps and Shells do Sails well found
 Topsides " Ceiling do Anchors, No. of 3 B. 1 St. 2 Keds.
 Wales " Rudder good Cables complete
 Plank (Bottom) and Counter " Copper or F.M. Paint When put on now Hawser and Warps "
 Caulking of Bottom, Deck, & Waterways good Standing and Running Rigging "
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers do Cargo and Main Hatchways good Hatches "

General Observations, Opinion as to Class, &c.
Bottom cleaned & painted. - Surveyed with ballast in hold. -
She is now in good, efficient condition & eligible in our opinion to remain as classed. -
 Committee's Minute 1st November, 1878.
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18