

REPORT of SURVEY for REPAIRS, &c.

No. *4414* Survey held at *Newport* Date, first Survey *21st Feb. 1878* Last Survey *21st Feb. 1878*
 Reg. Book. *215* on the *S.S. "Orchis"* Master *Parry*
 TONNAGE under Tonnage Deck *1712* Built at *Glasgow* When built *1870* YEAR. MONTH.
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage *1765* Owners *Mr. Johnston & Co* Port belonging to *Liverpool*
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St^rmer, cut on Bm. *1138* Residence *Liverpool*
 By whom built *Larrie* Destined Voyage *Savannah*
 Surveyed Afloat or in Dry Dock *Alexandra Dry Dock*

Length of Poop *ft.* Ditto, Forecastle *ft.* Ditto, Raised Quarter Deck *ft.* Years assigned. Character in Register Book.
 Last Survey, No. *19967* Port *Iron* Classed *100 A 1*
S.S. No 1 178

REPAIRS, OR EXAMINATION AS PER RULE *On acct of Grounding.*
Placed on blocks in Dry Dock, for examination of Bottom. No
apparent damage beyond the abrasion of paint, and the tips broken
off two of the propeller blades.
Now done. Two Propeller blades repaired, some rivets renewed in the
Rudder plating, and the Bottom well cleaned, and coated with
Patent Composition.

Present Condition of the	<i>Good</i>	<i>Tree-nails</i>	<i>Ports where seen</i>	<i>Good</i>	Windlass and Capstan	
Decks		Breasthooks and Stenson			Pumps	<i>Soft</i>
Waterways		Transoms, Pointers, and Crutches			Boats	<i>as</i>
Comings		Timbers of the Frame at the openings			Masts, Yards, &c.	<i>seen</i>
Upper Deck Beams & Fastenings		Ditto Ditto at other places			Condition, how ascertained	
Lower Deck Beams & Fastenings		Keelsons			Sails	<i>Good</i>
Planksheers		Clamps and Shelves <i>Shingles &c</i>			Anchors No. of	<i>and</i>
Sheerstrakes		Ceiling			Cables	<i>luff</i>
Topsides <i>Rating</i>		Rudder			Hawsers and Warps	
Wales		Copper <i>Paint</i> When put on <i>now</i>			Standing & Running Rigging	
Plank (Bottom) and Counter		Caulking of				
		Bottom, Deck, & Waterways		<i>Good</i>		
Engine Room Skylights		Coal Bunker, Openings, Lids, &c.			Cargo and Main Hatchways	
		Scuppers			Hatches	

General Observations, Opinion as to Class, &c. *eligible*
The vessel appears in good condition to remain as classed
100 A 1

The Amount of Entry Fee ... £ : : received by me, *4/11 1878*
 Special ... £ 2 : 2 :
 Certificate (if required) ... £ : :
 (Travelling Expenses, if any, £)
 Committee's Minute *8th November, 1878*
 Character assigned *100 A 1*
TRM
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 © 2019 Lloyd's Register Foundation

Archis



© 2019

Lloyd's Register
Foundation