

ANNUAL SURVEYS.

No. 26257 Survey held at Liverpool Date, first Survey 6 Aug. Last Survey 19th Sept 1878
 No. in on the Bk. "Unicorn" Master McCallum
 Reg. Book. 64 Tonnage 522 Built at Stockton When built 1863-9 mo
 By whom built Richardson Owners P. H. Dixon & Co
 Port belonging to Glasgow Destined Voyage
 If Surveyed Afloat or in Dry Dock Queen Q. Dock

Last Survey, No. 15739 Port of Liverpool Classed 2.76
 Present Condition of the Decks good Iron
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
Copper or Y.M. Cement When put on 69
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c.

App done - cleaned and recoated
This vessel is in good condition & eligible in my opinion to remain as classed
 Committee's Minute Liverpool Nov^r 8th 1878.
 Character assigned *A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1878

No. 277 Survey held at Liverpool Date, first Survey 9 Oct^r 78 Last Survey 19th Oct 1878
 No. in on the S. Agnes Oswald Master R. Mitchell
 Reg. Book. 277 Tonnage 1380 Built at Port Glasgow When built 1876-5 mo.
 By whom built Murray Owners D. Law
 Port belonging to Glasgow Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Queen Q. Dock

Last Survey, No. 16350 Port of Liverpool Classed 100 A1
 Present Condition of the Decks good Iron
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
Copper or Y.M. Cement When put on 76
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c.

This vessel has now been placed in proving dock, the bottom cleaned and painted - is in good condition & eligible in my opinion to remain as classed
 Committee's Minute Liverpool Nov^r 8th 1878.
 Character assigned 100 A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1878

Unicorn
Agnes Oswald
26257.



© 2019

Lloyd's Register
Foundation