

# ANNUAL SURVEYS.

22183 *27/85*

No.            Survey held at London Date, first Survey Nov 12 Last Survey Nov 23 1878  
 No. in on the SS Arcot Master             
 Reg. Book. 1173 Tonnage 1182 Built at Sumbarton When built 1870. 12-M  
 By whom built Jenny Owners British India Steamer Co.  
 Port belonging to Glasgow Destined Voyage             
 If Surveyed Afloat or in Dry Dock By J. & M. Limited

Last Survey, No. 20639 Port of Iron Classed 100A 2.78  
Years assigned. Character in Register Book.  
 Present Condition of the Decks Good Treenails Rivets Good  
 Waterways            Breasthooks and Stemson             
 Comings            Transoms, Pointers, and Crutches            Windlass and Capstan             
 Upper Deck Beams & Fastenings            Timbers of the Frame at the Openings            Pumps             
 Lower Deck Beams & Fastenings            Ditto ditto at other places            Boats             
 Planksheers            Keelsons            Masts, Yards, &c. Good & Sufficient  
 Sheerstrakes            Clamps and Shelves            Condition, how ascertained where they  
 Topsides            Ceiling            Sails             
 Wales            Rudder            Anchors, No. of 3 Bras. 12. 1/2 They could be seen  
 Plank (Bottom) and Counter            Copper or Y.M. Coated When put on Iron Cables             
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom scraped & coated.  
 Standing and Running Rigging           

*She is now in good condition and entitled to remain as classed.*

Senhouse Martin & Co.

Committee's Minute 21th November, 1878.  
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)            Paid            18           

No.            Survey held at London Date, first Survey Nov 9 Last Survey Nov 11th 1878  
 No. in on the SS Eldorado Master             
 Reg. Book. 256 Tonnage 2157 Built at Hull When built 1873 3M  
 By whom built 3382 Carlo Owners A Gray & E S Daves.  
 Port belonging to Glasgow Destined Voyage             
 If Surveyed Afloat or in Dry Dock By J. & M. Limited

Last Survey, No. 20195 Port of Iron Classed 100A 2.78  
Years assigned. Character in Register Book.  
 Present Condition of the Decks Good Treenails Rivets Good  
 Waterways            Breasthooks and Stemson             
 Comings            Transoms, Pointers, and Crutches            Windlass and Capstan             
 Upper Deck Beams & Fastenings            Timbers of the Frame at the Openings            Pumps             
 Lower Deck Beams & Fastenings            Ditto ditto at other places            Boats             
 Planksheers            Keelsons            Masts, Yards, &c. Good & Sufficient  
 Sheerstrakes            Clamps and Shelves            Condition, how ascertained where they  
 Topsides            Ceiling            Sails             
 Wales            Rudder            Anchors, No. of 3 Bras. 12. 1/2 They could be seen  
 Plank (Bottom) and Counter            Copper or Y.M. Coated When put on Iron Cables             
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom scraped & coated.  
 Standing and Running Rigging           

*She is now in good condition and entitled to remain as classed.*

Senhouse Martin & Co.

Committee's Minute 21th November, 1878.  
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)            Paid            18