

# ANNUAL SURVEYS.

No. 22184 Survey held at London Date, first Survey 30th Oct Last Survey 15th Novr. 1878.  
 No. in on the Bk. "Astarte" Master G. J. Parsons  
 Reg. Book. 1369 Tonnage 910 Built at Glasgow When built 1877 9th mo.  
 By whom built Barclay Owners J. Shepherd & Co.  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed ~~Afloat~~ in Dry Dock West India

Last Survey, No. 19407 Port of London Classed 100 A1  
 Present Condition of the  
 Decks Good Transoms Rivets Good where seen  
 Waterways do Breasthooks and Stemson do  
 Comings do Transoms, ~~Pointers~~, and Crutches do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do  
 Planksheers do Keelsons do  
 Sheerstrakes do Clamps and Shetfs do  
 Topsides do Ceiling do  
 Wales do Rudder good  
 Plank (Bottom) and Counter do Copper or F.M. Paint When put on now  
 Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights do Coal Bunkers, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways good Hatches do

General Observations, Opinion as to Class, &c.  
Bottom cleaned & repainted. Surveyed with outward cargo in hold.  
She is now in good, efficient condition and eligible in our opinion to remain as classed.

Committee's Minute 3rd December, 1878, H. Paulsen.  
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. 20916 Survey held at London Date, first Survey 18th Novr. Last Survey 16th Novr. 1878.  
 No. in on the S. S. "Semiramide" Master J. H. Brown  
 Reg. Book. 529 Tonnage 1165 Built at Newcastle When built 1877 9th mo.  
 By whom built Mitchell Owners H. R. Gully  
 Port belonging to Newcastle Destined Voyage \_\_\_\_\_  
 If Surveyed ~~Afloat~~ in Dry Dock Millwall Dry Dock

Last Survey, No. 20916 Port of London Classed 100 A1  
 Present Condition of the  
 Decks Good Transoms Rivets Good where seen  
 Waterways do Breasthooks and Stemson do  
 Comings do Transoms, ~~Pointers~~, and Crutches do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do  
 Planksheers do Keelsons do  
 Sheerstrakes do Clamps and Shetfs do  
 Topsides do Ceiling do  
 Wales do Rudder good  
 Plank (Bottom) and Counter do Copper or F.M. Paint When put on now  
 Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers do Cargo and Main Hatchways good Hatches do

General Observations, Opinion as to Class, &c.  
Bottom cleaned & repainted. Surveyed with dunnage wood etc. in hold.  
She is now in good, efficient condition & eligible in our opinion to remain as classed.

Committee's Minute 3rd December, 1878, H. Paulsen.  
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18