

ANNUAL SURVEYS.

No. 4187 Survey held at Dundee Date, first Survey Dec 2nd Last Survey Dec 2nd 18 78
 No. in on the Iron Ship "Star of Greece" Master Legg
 Reg. Book. 1036 Tonnage 122 1/2 Built at Belfast When built 1868 - 9ms
 By whom built Harland Owners J. Corry & Co
 Port belonging to Belfast Destined Voyage Shields to load for Calcutta
 If Surveyed Afloat or in Dry Dock In dry dock with ballast and dunnage onboard

Last Survey, No. 18165 Port of Iron Classed ss. Low No. 2 - 76
 Present Condition of the
 Decks Good Treenails Good Rivets Good
 Waterways Butler Breasthooks and Stenson Good
 Comings Good Transoms, Pointers, and Crutches Where
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Seen
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Stringers Good
 Topsides Good Ceiling Where seen good
 Wales Good Rudder Good & efficient
 Plank (Bottom) and Counter Good Copper or Y.M. Cement When put on 168
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Vessel placed on blocks; keel bottom & sides cleaned down & examined; renewed the fore topgallt yard and altered trusses where required; recoated bottom & sides.
This vessel is now where seen in good & efficient condition and eligible in my opinion to remain as Classed.
 Committee's Minute 13th December, 1878
 Character assigned A 1 J. L. Dinnette
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stenson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18