

ANNUAL SURVEYS.

No. 1050 Survey held at London Date, first Survey Dec 25 Last Survey Dec 12 1878
 No. in on the S Star of Persia Master J Barry Esq
 Reg. Book. 1050 Tonnage 1227 Built at Belfast When built 1868 6M
 By whom built Harland Owners J Barry Esq
 Port belonging to Belfast Destined Voyage
 If Surveyed Afloat or in Dry Dock Green's Dry Dock

Last Survey, No. 18803 Port of Iron Classed A1 6.77
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights " Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom scraped & coated

She is now in good condition and entitled to remain as classed

Committee's Minute 17th December, 1878.

Character assigned A1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. 538 Survey held at London Date, first Survey Dec 3 Last Survey Dec 5 1878
 No. in on the SS Dunrobin Castle Master J Harrison
 Reg. Book. 538 Tonnage 1784 Built at Glasgow When built 1875 11M
 By whom built Napier Owners J Burnie Esq
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock James's Dock & Dry Dock

Last Survey, No. 20944 Port of Iron Classed 100A 5.78
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom scraped & coated

She is now in good condition and entitled to remain as classed

Committee's Minute 17th December, 1878.

Character assigned 100A

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18