

ANNUAL SURVEYS.

No. 22340 Survey held at London Date, first Survey 23rd Novr. Last Survey 23rd Novr. 1878
 No. in on the S. S. "Jerviot" Master H. Nisbet
 Reg. Book. 167 Tonnage 1262 Built at Sunderland When built 1871 6 mo
 By whom built 1886 Laing Owners C. M. Normood & Co.
 Port belonging to London Destined Voyage
 If Surveyed Afloat in Dry Dock Millwall Dry Dock

Last Survey, No. 19766 Port of Iron Classed 100 A1
 Present Condition of the
 Decks Good Transoms Rivets Good where seen
 Waterways " Breasthooks and Stems do
 Comings " Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings " Ditto ditto at other places do
 Planksheers " Keelsons do
 Sheerstrakes " Clamps and Sticks "
 Topsides " Ceiling do
 Wales " Rudder good
 Plank (Bottom) and Counter " Copper or F.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers " Cargo and Main Hatchways good Hatches "
 General Observations, Opinion as to Class, &c.,

Rudder braces bushed. - Bottom cleaned & repainted. -
Surveyed with dunnage wood etc in hold. -
She is now in good, efficient condition & eligible in my opinion to remain as classed.

Committee's Minute 6th December, 1878. H. Paulsen.
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
TBW Certificate (if required) Paid 18

No. 22340 Survey held at London Date, first Survey 21st Novr. Last Survey 21st Novr. 1878
 No. in on the S. S. "Walmer Castle" Master C. Young
 Reg. Book. 45 Tonnage 1594 Built at Glasgow When built 1872 4 mo
 By whom built 2385 Barclay Owners D. Currie & Co.
 Port belonging to London Destined Voyage
 If Surveyed Afloat in Dry Dock West Ind. Dry Dock

Last Survey, No. 21321 Port of Iron Classed 100 A1
 Present Condition of the
 Decks Good Transoms Rivets Good
 Waterways " Breasthooks and Stems "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Sticks "
 Topsides " Ceiling "
 Wales " Rudder good
 Plank (Bottom) and Counter " Copper or F.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers " Cargo and Main Hatchways good Hatches "
 General Observations, Opinion as to Class, &c.,

Bottom cleaned & repainted. -
She is now in good, efficient condition & eligible in our opinion to remain as classed. -

Committee's Minute 6th December, 1878. H. Paulsen.
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
TBW Certificate (if required) Paid 18