

# ANNUAL SURVEYS.

No. 26310 Survey held at Liverpool Date, first Survey 14<sup>th</sup> Oct. Last Survey 30<sup>th</sup> Oct. 1878  
 No. in on the 5<sup>th</sup> "Aurora" Master Black  
 Reg. Book. 1084 Tonnage 144 3 Built at P. Glasgow When built 1866-8 mo.  
 By whom built Reid Owners J. Heaps & Son  
 Port belonging to Liverpool Destined Voyage  
 If Surveyed Afloat or in Dry Dock Lucan G. Rd

Last Survey, No. 19780 Port of Liverpool Classed 12.44 Character in Register Book. \*A1  
 Present Condition of the  
 Decks good Rivets iron  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper on Y.M. Cement When put on 66  
 Caulking of Bottom, Deck, & Waterways iron  
 Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers iron Cargo and Main Hatchways iron Hatches iron

General Observations, Opinion as to Class, &c.

*This vessel has now been placed in graving dock - the bottom cleaned and painted - is in iron condition & eligible in my opinion to remain as classed*

Committee's Minute

Liverpool Dec<sup>r</sup> 27-1878  
\*A1

Character assigned

Geo. T. Cooper  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. 426 Survey held at Liverpool Date, first Survey 25<sup>th</sup> Nov<sup>r</sup> Last Survey 11<sup>th</sup> Dec<sup>r</sup> 1878  
 No. in on the 5<sup>th</sup> "Aldborough" Master Andrews  
 Reg. Book. 1425 Tonnage 1472 Built at Stockton When built 1875-1 mo  
 By whom built Richardson Owners Brit. & East. Ship Co. (Lim)  
 Port belonging to Liverpool Destined Voyage Melbourne  
 If Surveyed Afloat or in Dry Dock Brunswick G. Rd

Last Survey, No. 19117 Port of Liverpool Classed 100 A1 Character in Register Book. 8.44  
 Present Condition of the  
 Decks good Rivets iron  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper on Y.M. Cement When put on 75  
 Caulking of Bottom, Deck, & Waterways iron  
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers iron Cargo and Main Hatchways iron Hatches iron

General Observations, Opinion as to Class, &c.

*This vessel has now been placed in graving dock - the bottom cleaned & painted, is in iron condition & eligible in my opinion to remain as classed*

Committee's Minute

Liverpool Dec<sup>r</sup> 27-1878.  
100 A1

Character assigned

Geo. T. Cooper  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18



Antiope  
Aldbrough  
26310



© 2019

Lloyd's Register  
Foundation