

ANNUAL SURVEYS.

No. 26308 Survey held at Liverpool Date, first Survey Dec 7th Last Survey Dec 9th 1878.
 No. in Reg. Book. 21. on the Bark "Mabel Young" Master J. S. Crane.
 Tonnage 1016 Built at Glasgow When built 1877 - 11 mo
 By whom built Stephen Owners Hellick Martin & Co.
 Port belonging to London Destined Voyage Calcutta.
 If Surveyed Afloat or in Dry Dock Sandon Dry Dock.

Last Survey, No. 19855 Port of Liverpool Classed 100 AI 12.77.
 Present Condition of the Decks Good
 Waterways ✓ Transoms Good
 Comings ✓ Ribs Good
 Upper Deck Beams & Fastenings ✓ Transoms, Pointers, and Crutches ✓
 Lower Deck Beams & Fastenings ✓ Timbers of the Frame at the Openings ✓
 Planksheers ✓ Ditto ditto at other places ✓
 Sheerstrakes ✓ Keelsons ✓
 Topsides ✓ Clamps and Shells ✓
 Wales ✓ Ceiling ✓
 Plank (Bottom) and Counter ✓ Rudder ✓
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Copper or Y.M. Cement When put on 77
 General Observations, Opinion as to Class, &c. Good
 Bottom, Deck, & Waterways Good
 Scuppers Good Cargo and Main Hatchways Good Hatches Good
 Windlass and Capstan Good.
 Pumps ✓
 Boats ✓
 Masts, Yards, &c. ✓
 Condition, how ascertained from on board
 Sails Good
 Anchors, No. of and
 Cables and
 Hawesers and Warps Sufficient.
 Standing and Running Rigging Sufficient.

Committee's Minute Liverpool Dec^r 27th 1878
 Character assigned 100 AI.
 T. Shilston -
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. ✓ Survey held at Liverpool Date, first Survey Dec 7th Last Survey Dec 9th 1878.
 No. in Reg. Book. 162 on the Ship "Lake Erie" Master Sclater.
 Tonnage 938 Built at Glasgow When built 1868 - 12 mo.
 By whom built Barclay Owners Canada Sh. Co. (Lim)
 Port belonging to Montreal Destined Voyage Portland, Maine.
 If Surveyed Afloat or in Dry Dock Sandon Dry Dock.

Last Survey, No. 17964 Port of Liverpool Classed S.S. Cl. N° 2.77. 3.77.
 Present Condition of the Decks Good
 Waterways ✓ Transoms Good
 Comings ✓ Ribs Good
 Upper Deck Beams & Fastenings ✓ Transoms, Pointers, and Crutches ✓
 Lower Deck Beams & Fastenings ✓ Timbers of the Frame at the Openings ✓
 Planksheers ✓ Ditto ditto at other places ✓
 Sheerstrakes ✓ Keelsons ✓
 Topsides ✓ Clamps and Shells ✓
 Wales ✓ Ceiling ✓
 Plank (Bottom) and Counter ✓ Rudder ✓
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Copper or Y.M. Cement When put on 68.
 General Observations, Opinion as to Class, &c. Good
 Bottom, Deck, & Waterways Good
 Scuppers Good Cargo and Main Hatchways Good Hatches Good
 Windlass and Capstan Good.
 Pumps ✓
 Boats ✓
 Masts, Yards, &c. ✓
 Condition, how ascertained from on board
 Sails Good
 Anchors, No. of and
 Cables and
 Hawesers and Warps Sufficient.
 Standing and Running Rigging Sufficient.

Committee's Minute Liverpool Dec^r 27th 1878.
 Character assigned * AI.
 T. Shilston -
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

Nabel Young
Lake Erie
26308.



© 2019

Lloyd's Register
Foundation