

22504 ANNUAL SURVEYS.

No. 22504 Survey held at London Date, first Survey Jan 4 Last Survey Jan 6 1879
 No. in on the SS Gleniffer Master
 Reg. Book. 1412 Tonnage 1412 Built at Sunderland When built 1877 Memo
 By whom built Mounsey Owners M'Gregor Gow & Co
 Port belonging to Glasgow Destined Voyage
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 21159 Port of Bron Classed 100A/578
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " ~~Copper or Y.M. Coated~~ When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom scraped and coated.

She is now in good condition and entitled to remain as classed.

Committee's Minute 17th January, 1879
 Character assigned 100A/578
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. 19804 Survey held at London Date, first Survey Dec 28/78 Last Survey Dec 28/78 1878
 No. in on the SS Queen Victoria Master J. Sangster
 Reg. Book. 32 Tonnage 1384 Built at Sunderland When built 1872 1M
 By whom built Sliff Owners Queen Stn Ship Co.
 Port belonging to Glasgow Destined Voyage
 If Surveyed Afloat or in Dry Dock Blackwall Point Dry Dock

Last Survey, No. 19804 Port of Bron Classed 100A/1177
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " ~~Copper or Y.M. Coated~~ When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom scraped and coated.

She is now in good condition and entitled to remain as classed.

Committee's Minute 17th January, 1879
 Character assigned 100A/1177
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18