

22525

ANNUAL SURVEYS.

No. 22525 Survey held at London Date, first Survey 30th Nov Last Survey 5 Decr 1878
No. in on the Barge Myrtle Holme Master James Ritchie
Reg. Book. 1363 Tonnage 902 Built at Sunderland When built 1875 — 6 mo.
By whom built Bartram Owners Nine Bro.
Port belonging to Warrington Destined Voyage
If Surveyed Afloat or in Dry Dock Since by dock & afloat

Last Survey, No. 19301 Port of Iron Classed 100 A1
Present Condition of the Decks Good Treennails Good Rivets Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " ~~Timbers~~ of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder rebushed.
Plank (Bottom) and Counter " Copper or Y.M. When put on 1875
Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches "
General Observations, Opinion as to Class, &c.

The Bottom sighted, scraped and recoated. Rudder unhung and pintles rebushed. Main Topmast renewed.

This vessel is now in good & efficient condition and eligible to continue as at present classed.

Committee's Minute 10th January 1879.

Character assigned 100 A1

A. Edwards.
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

No. 22525 Survey held at London Date, first Survey 26 Nov Last Survey 28th Decr 1878
No. in on the BK "Carmelo" Master Robt Mc Clure
Reg. Book. 279 Tonnage 689 Built at Sunderland When built 1876 — 4 mo
By whom built Austin & Hunter Owners G. I. Hay
Port belonging to Sunderland Destined Voyage
If Surveyed Afloat or in Dry Dock Welson by dock & afloat

Last Survey, No. 19255 Port of Iron Classed 100 A1
Present Condition of the Decks Good Treennails Good Rivets Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " ~~Timbers~~ of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. When put on 1876
Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c.

Bottom cleaned & recoated. one new boat supplied. This vessel appears to be in good and efficient condition and eligible to continue as at present classed — viz 100 A1 —

Committee's Minute 10th January 1879.

Character assigned 100 A1

A. Edwards.
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18