

ANNUAL SURVEYS.

No. 22664 Survey held at London Date, first Survey 16th Jan. Last Survey 17th Jan. 1879
 No. in on the Barge "Star of Albion" Master I. Hughes
 Reg. Book. 1026 Tonnage 999 Built at Belfast When built 1864 7th mo.
 By whom built Harland Owners I. Curry & Co.
 Port belonging to Belfast Destined Voyage
 If Surveyed ~~Afloat~~ in Dry Dock Canal Dry Dock

Last Survey, No. 19542 Port of Ron Classed *A1
 Present Condition of the Decks Good Freeboards Rivets Good where seen
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shells do
 Topsides do Ceiling do
 Wales do Rudder good
 Planks (Bottom) and Counter do Copper or F.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights do Coal Bunker, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways good Hatches do

General Observations, Opinion as to Class, &c.
Rig of vessel altered into a barge. New Mizen topmast.
Rudder pintles bushed; Bottom cleaned & repainted.
Surveyed with ballast in hold.
This vessel is now in good condition & in our opinion eligible to remain as classed.
 Committee's Minute 31st January, 1879,
 Character assigned *A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 22664 Survey held at London Date, first Survey 18th Jan. Last Survey 20th Jan. 1879
 No. in on the Bk. "Glen Caladh" Master R. Lamont
 Reg. Book. 408 Tonnage 494 Built at Glasgow When built 1876 5th mo.
 By whom built Dobie Owners R. Lamont
 Port belonging to Glasgow Destined Voyage
 If Surveyed ~~Afloat~~ in Dry Dock West India Dry Dock

Last Survey, No. 19588 Port of Ron Classed 100 A1
 Present Condition of the Decks Good Freeboards Rivets Good where seen
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shells do
 Topsides do Ceiling do
 Wales do Rudder good
 Planks (Bottom) and Counter do Copper or F.M. Paint When put on now
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights do Coal Bunkers, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways good Hatches do

General Observations, Opinion as to Class, &c.
Bottom cleaned & repainted.
Surveyed with ballast in hold.
This vessel is now in good condition and eligible in our opinion to remain as classed.
 Committee's Minute 31st January, 1879,
 Character assigned 100A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18