

ANNUAL SURVEYS.

22719
Rec 17/2/79

No. in Reg. Book. **No. 2711** Survey held at **Swansea** Date, first Survey **13th Jan^r** Last Survey **14th Jan^r** 1879
on the **S S "Reneil"** Master **Auffret**

262 Tonnage **300** Built at **Newcastle** When built **1878 - 5th mo**

By whom built **Leslie** Owners **J. Lamy, fils**

Port belonging to **Caen** Destined Voyage **Caen**

If Surveyed ~~Afloat~~ or in Dry Dock **Jersey Dry Dock**

Last Survey, No. **20750** Port of **Rouen**

Classed **90A1**
Years assigned. **4-78**
Character in Register Book.

Present Condition of the

Decks **Good**

Greenails Rivets **Good**

Waterways **"**

Breasthooks and Stems **"**

Comings **"**

Transoms, Pointers, and Crutches **"**

Upper Deck Beams & Fastenings **"**

Timbers of the Frame at the Openings **"**

Lower Deck Beams & Fastenings **"**

Ditto ditto at other places **"**

Planksheers **"**

Keelsons **Not seen**

Sheerstrakes **"**

Clamps and Shelves **"**

Topsides **"**

Ceiling **"**

Wales **"**

Rudder **"**

Plank (Bottom) and Counter **"**

Copper or ~~V.M.~~ Coated When put on **Now**

Caulking of **"**

Bottom, Deck, & Waterways **Good**

Engine Room Skylights **Good** Coal Bunker, Openings, Lids, &c. **Good** Scuppers **"** Cargo and Main Hatchways **Good** Hatches **"**

General Observations, Opinion as to Class, &c. **This vessel grounded at Caen on some hard substance which caused a small fracture in one garb² plate on the Port side, a piece of plate has been fitted over the fracture and well riveted. The bottom has now been coated. She is in good condition and eligible to remain as belassed.**

Committee's Minute **18th February, 1879.**

Character assigned **90A1**

Thos. Ashton

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) **2-2-0 Paid 14th Feb^r 1879**

1879-0438

No 2711 Swansea

2711/1/1



© 2019

Lloyd's Register
Foundation