

ANNUAL SURVEYS.

22705

No. 26371 Survey held at Liverpool Date, first Survey Feb 3rd Last Survey Feb 4th 1879
 No. in on the Bark "Lindores Abbey" Master Mitchinson
 Reg. Book. 472 Tonnage 863 Built at D. Glasgow When built 1877 - 1 mo.
 By whom built Duncan Owners J. Renton.
 Port belonging to Glasgow Destined Voyage Calcutta.
 If Surveyed Afloat or in Dry Dock Princes Dry Dock.

Last Survey, No. 14692 Port of Iron Classed 100 AI
 Present Condition of the Decks Good Treenails Rivets. Good
 Waterways ✓ Breasthooks and Stenson ✓
 Comings ✓ Transoms, Pointers, and Crutches ✓
 Upper Deck Beams & Fastenings ✓ Timbers of the Frame at the Openings ✓
 Lower Deck Beams & Fastenings ✓ Ditto ditto at other places ✓
 Planksheers ✓ Keelsons ✓
 Sheerstrakes ✓ Clamps and Shells ✓
 Topsides ✓ Ceiling ✓
 Wales ✓ Rudder ✓
 Plank (Bottom) and Counter ✓ Copper or Y.M. Cement When put on 77
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Caulking of Bottom, Deck, & Waterways Good
 General Observations, Opinion as to Class, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good

Bottom examined cleaned and coated with paint and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool Feb 25th 1879 Character assigned 100 AI.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18

No. ✓ Survey held at Liverpool Date, first Survey Feb 6th Last Survey Feb 7th 1879.
 No. in on the Schooner "Rotterdam" Master M Callaghan
 Reg. Book. 668 Tonnage 414 Built at Dumbarton When built 1856 - 10 mo.
 By whom built Penny Owners Sir J. Malcolm
 Port belonging to London Destined Voyage Oporto.
 If Surveyed Afloat or in Dry Dock Sandon Dry Dock

Last Survey, No. 19520 Port of Iron Classed 100 AI
 Present Condition of the Decks Good Treenails Rivets. Good S.S. Lon. No 377. 9.77.
 Waterways ✓ Breasthooks and Stenson ✓
 Comings ✓ Transoms, Pointers, and Crutches ✓
 Upper Deck Beams & Fastenings ✓ Timbers of the Frame at the Openings ✓
 Lower Deck Beams & Fastenings ✓ Ditto ditto at other places ✓
 Planksheers ✓ Keelsons ✓
 Sheerstrakes ✓ Clamps and Shells ✓
 Topsides ✓ Ceiling ✓
 Wales ✓ Rudder ✓
 Plank (Bottom) and Counter ✓ Copper or Y.M. Cement When put on 15/77.
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Caulking of Bottom, Deck, & Waterways Good
 General Observations, Opinion as to Class, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good

Bottom examined cleaned and coated with paint and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool Feb 25th 1879 Character assigned 100 AI.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) ✓ Paid 18

Lindores Abbey
Rotterdam

ss

26371.



© 2019

Lloyd's Register
Foundation