

ANNUAL SURVEYS. 22499 37890

No. 50 Survey held at London Date, first Survey 17.2.79 Last Survey 19.2.79 18
 No. in on the S.S. Hankow Master Symington
 Reg. Book. 3332 Tonnage 3594 Built at Burcastle When built 1873 - 10th mo
 By whom built Mitchell Owners Hatts, Milburn & Co
 Port belonging to London Destined Voyage West India Dry Dock
 If Surveyed Afloat or in Dry Dock West India Dry Dock

Last Survey, No. 21702 Port of Ron Classed 100 A.1.
 Present Condition of the
 Decks good Rings where run, good
 Waterways do Breasthooks do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings good
 Lower Deck Beams & Fastenings do Ditto ditto at other places not run
 Planksheers do Keelsons where run, good
 Sheerstrakes Plating good Clamps and Shells do
 Topsides do Ceiling do
 Wales do Rudder good
 Plating (Bottom) and Counter good Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers do Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. This vessel has been placed in dry dock, bottom cleaned & recoated with 2 coats of white line & white zinc & tallow. Part cargo in hold. Vessel appears in good condition & is eligible, in our opinion, to remain as classed.

Committee's Minute 28th February, 1879
 Character assigned 100 A.1.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 209 Survey held at London Date, first Survey 18.2.79 Last Survey 20.2.79 18
 No. in on the S.S. Lapland Master Potts
 Reg. Book. 1262 Tonnage 1262 Built at Glasgow When built 1872 - 9th mo
 By whom built Barday Owners Leith, Hull & Hamburg Ste
 Port belonging to Leith Destined Voyage Canal Dry dock & Afloat
 If Surveyed Afloat or in Dry Dock Canal Dry dock & Afloat

Last Survey, No. 18073 Port of Ron Classed 100 A.1.
 Present Condition of the
 Decks good Rings where run, good
 Waterways do Breasthooks do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons where run, good
 Sheerstrakes Plating do Clamps and Shells do
 Topsides do Ceiling do
 Wales do Rudder good
 Plating (Bottom) and Counter do Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers do Cargo and Main Hatchways good Hatches do
 General Observations, Opinion as to Class, &c. Vessel has been placed in dry dock, bottom cleaned & recoated. Rudder lifted & brushed. Vessel appears in good condition and is eligible, in our opinion, to remain as classed.

Committee's Minute 28th February, 1879
 Character assigned 100 A.1.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18