

# ANNUAL SURVEYS. 22800

No. 26376 Survey held at Liverpool Date, first Survey 23<sup>rd</sup> Jan Last Survey 8<sup>th</sup> Feb. 1879  
 No. in on the S. "Glenary" Master H. Millard  
 Reg. Book. 464 Tonnage 1769 Built at Liverpool When built 1873-10 mo  
 By whom built Royden Owners R. Alexander & Co  
 Port belonging to Liverpool Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Queen G. On

Last Survey, No. 19468 Port of Iron  
 Present Condition of the  
 Decks good Timber Rails good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
Plank (Bottom) and Counter " Copper or Y.M. Cement When put on 73  
 Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c.

This vessel has now been placed in graving dock the bottom cleaned & painted, is in good condition, & eligible in my opinion, to remain as classed

Committee's Minute Liverpool March 2<sup>nd</sup> 1879.  
 Character assigned 100 A1.

Geo. T. Cooper  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) — Paid — 18 —

No. — Survey held at Liverpool Date, first Survey 6<sup>th</sup> Feb Last Survey 27<sup>th</sup> Feb 1879  
 No. in on the Bk. "Shakespeare" Master D. Hughes  
 Reg. Book. 582 Tonnage 767 Built at Liverpool When built 1876-4 mo.  
 By whom built Evans Owners B. C. Friend & Co  
 Port belonging to Liverpool Destined Voyage Adelaide  
 If Surveyed Afloat or in Dry Dock Queen G. On

Last Survey, No. 16443 Port of Iron  
 Present Condition of the  
 Decks good Timber Rails good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
Plank (Bottom) and Counter " Copper or Y.M. Cement When put on 76.  
 Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c.

This vessel has now been placed in graving dock - the bottom cleaned and painted - is in good condition & eligible in my opinion, to remain as classed

Committee's Minute Liverpool March 2<sup>nd</sup> 1879.  
 Character assigned 100 A1.

Geo. T. Cooper  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) — Paid — 18 —



"Glenganny"  
"Shakespeare"

26 346



© 2019

Lloyd's Register  
Foundation