

No. 1103 on the S Millwall Date, first Survey Jan 23 1879 Feb 3rd 1879
Reg. Book. 1103 Tonnage 1165 Built at London Master R Muir 37892
By whom built Millwall I. W. Co. Owners J. Duncan
Port belonging to Liverpool Destined Voyage
If Surveyed Afloat or in Dry Dock Blackwall Point Dry Dock

Last Survey, No. 18596 Port of Iron Classed TA 1 6.77
SS Liv M3.77

Present Condition of the

Decks	<u>Good</u>	Treenails <u>Pivots</u>	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"
Planksheers	"	Keelsons	"
Sheerstrakes	"	Clamps and Shelves	"
Topsides	"	Ceiling	"
Wales	"	Rudder	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Coated</u> When put on <u>Now</u>	
Engine Room Skylights	<u>-</u>	Caulking of Bottom, Deck, & Waterways	
Coal Bunkers, Openings, Lids, &c.		Scuppers <u>Good</u>	Cargo and Main Hatchways <u>Good</u>
General Observations, Opinion as to Class, &c.		Hatches <u>Good</u>	

Windlass and Capstan
Pumps
Boats
Masts, Yards, &c.
Condition, how ascertained
Sails
Anchors, No. of 3 Breeches & Kedge
Cables
Hawsers and Warps
Standing and Running Rigging

Good ?
Sufficient
where
they
could
be run

Bottom Scraped and coated.
She is now in good condition
and entitled to remain as classed.

Committee's Minute 4th March, 1879.

Character assigned TA 1

JRM

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18