

# ANNUAL SURVEYS.

22855 37.9.12

No. 553 Survey held at London Date, first Survey 19th Febr. Last Survey 21st Febr. 1879.  
 No. in on the Ship "Serapis" Master J. Pankhurst  
 Reg. Book. 553 Tonnage 995 Built at Greenock When built 1876 10th mo.  
 By whom built Scott Owners H. Lund  
 Port belonging to London Destined Voyage  
 If Surveyed Afloat or in Dry Dock Britannia Dry Dock.

Last Survey, No. 20215 Port of Iron Classed 100 A1  
 Present Condition of the Decks Good Transoms Rivets Good where seen  
 Waterways " Breasthooks and Stems do  
 Comings " Transoms, Pointers, and Crutches do  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings " Ditto ditto at other places do  
 Planksheers " Keelsons do  
 Sheerstrakes " Clamps and Shelves  
 Topsides " Ceiling do  
 Wales " Rudder good  
 Planks (Bottom) and Counter " Copper or F.M. Paint When put on now  
 Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c.

Bottom cleaned & repainted.  
Surveyed with ballast in hold.

She is now in good condition and eligible in my opinion to remain as classed.

Committee's Minute 7th March, 1879. W. Paulsen  
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) T.B.W. Paid 18

No. 78 Survey held at London Date, first Survey 25th Febr. Last Survey 27th Febr. 1879.  
 No. in on the S. S. "Oceano" Master J. Walker  
 Reg. Book. 78 Tonnage 566 Built at Mdlsbr. When built 1871-8 mo.  
 By whom built Backhouse Owners Vatham & Co.  
 Port belonging to London Destined Voyage  
 If Surveyed Afloat or in Dry Dock Britannia Dry Dock.

Last Survey, No. 21413 Port of Iron Classed 100 A1  
 Present Condition of the Decks Good Transoms Rivets Good where seen  
 Waterways " Breasthooks and Stems do  
 Comings " Transoms, Pointers, and Crutches do  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings " Ditto ditto at other places do  
 Planksheers " Keelsons do  
 Sheerstrakes " Clamps and Shelves  
 Topsides " Ceiling do  
 Wales " Rudder good  
 Planks (Bottom) and Counter " Copper or F.M. Black Varnish When put on now  
 Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c.

Bottom cleaned & repainted.  
Surveyed with ballast in hold.

She is now in good condition and in my opinion eligible to remain as classed.

Committee's Minute 7th March, 1879. W. Paulsen  
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) T.B.W. Paid 18