

ANNUAL SURVEYS. 22859 37.9 11

No. 1051 Survey held at London Date, first Survey June 20 Last Survey Feb 28 1879
 No. in on the S Star of Russia Master J Simpson
 Reg. Book. 1051 Tonnage 1872 Built at Belfast When built 1874-12 M
 By whom built Harland Owners J Long & Co
 Port belonging to Belfast Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 20049 Port of Iron Classed 100A-4.78
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. bruted When put on new
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom bruted, 16 frames in sufficient strength additional angle iron put in them. She is now in good condition and entitled to remain as classed.

Committee's Minute 7th March. 1879. Senhouse Martinide
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. 785 Survey held at London Date, first Survey Feb 27 Last Survey Feb 27 1879
 No. in on the S Silvermore Master J Hughes
 Reg. Book. 785 Tonnage 1668 Built at Belfast When built 1878 2 M
 By whom built Harland Owners W P Sinclair & Co
 Port belonging to Liverpool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 20639 Port of Iron Classed 100A-3.78
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. bruted When put on new
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom bruted. She is now in good condition and entitled to remain as classed.

Committee's Minute 7th March. 1879. Senhouse Martinide
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____