

22866

Report of Survey for Repairs of Engines and Boilers.

No. 144

No. in Survey held at

South Shields

Date, first Survey

and

Last Survey

10th March 1879

475 on the Iron S.S. "Kerethick"

Master

Built at Newcastle

When built 1866 - 2 mcs.

Tons

489
749
726

Owners

J. Hensick & Son

Port belonging to

Newcastle

Classed

Years assigned.

Character in Register Book.

A 1
11.74

Diameter of Cylinders 26" 5"

Length of Stroke

30"

Engines made at

London

When made

1873

Pressure of Steam

75 lbs

Registered Horse Power

99

By whom made

Victoria Dock Works (Lancaster)

Particulars of Repairs and Examination

The Machinery of this vessel reported to be damaged by striking the breakwater on entering the Harbour of New Shields on Monday the 3rd March 1879 for particulars see Damage Report 10th March 1879. has been repaired and made satisfactory.

The Machinery of this vessel is now in good order and safe working condition, and eligible in my opinion to retain its class in the Society's Register Book.

The Amount of Fee ... £ 2 : 2 : - received by me,

Certificate (if required) ... £ - : - : - 14 Feb 1879

(Travelling Expenses, if any, £ -)

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

18

Lloyd's Register
Foundation

IRON483-0094

Lancaster Report No. 19465

(Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)

The Surveyors are requested not to write on or below the space for Committee's Minute.

5-1000, 22/7/73.]

It is submitted that this
asset is eligible to
remain as classified

M 17/3/75



© 2019

Lloyd's Register
Foundation