

# ANNUAL SURVEYS.

22899

No. 136/77 Survey held at London Date, first Survey March 8<sup>th</sup> Last Survey March 11<sup>th</sup> 1877  
 No. in on the SS Glenartney Master Hugh Auld  
 Reg. Book. 424 Tonnage 1371 Built at Glasgow When built 1873 S.M.  
 By whom built Sen & Glas Owners A & Gou & Co  
 Port belonging to Glasgow Destined Voyage  
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 21505 Port of Ron

Classed 100A 8.78  
 SS No 1-78

Present Condition of the		Treenails		Years assigned.		Character in Register Book.	
Decks	<u>Good</u>	<u>Rivets</u>	<u>Good</u>				
Waterways	"	Breasthooks and Stemson	"				
Comings	"	Transoms, Pointers, and Crutches	"				
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"				
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"				
Planksheers	"	Keelsons	"				
Sheerstrakes	"	Clamps and Shelves	"				
Topsides	"	Ceiling	"				
Wales	"	Rudder	"				
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Copper</u> When put on <u>Now</u>					
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>				
Coal Bunker, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>				
General Observations, Opinion as to Class, &c.	<u>Bottom coated</u>						

*She is now in good condition and entitled to remain as classed.*

Committee's Minute 18<sup>th</sup> March, 1879.

Character assigned 100A

Senhouse Martindale  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. 136/77 Survey held at London Date, first Survey Feb 22 Last Survey Feb 22 1879  
 No. in on the SS Walmer Castle Master J Webster & Young  
 Reg. Book. 45 Tonnage 1554 Built at Glasgow When built 1872 S.M.  
 By whom built Baird & Co Owners J Currie & Co  
 Port belonging to London Destined Voyage  
 If Surveyed Afloat or in Dry Dock Greens Dry Dock

Last Survey, No. 22340 Port of Ron

Classed 100A 8.78  
 SS Sen M 76

Present Condition of the		Treenails		Years assigned.		Character in Register Book.	
Decks	<u>Good</u>	<u>Rivets</u>	<u>Good</u>				
Waterways	"	Breasthooks and Stemson	"				
Comings	"	Transoms, Pointers, and Crutches	"				
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"				
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"				
Planksheers	"	Keelsons	"				
Sheerstrakes	"	Clamps and Shelves	"				
Topsides	"	Ceiling	"				
Wales	"	Rudder	"				
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Copper</u> When put on <u>Now</u>					
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>				
Coal Bunkers, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>				
General Observations, Opinion as to Class, &c.	<u>Bottom coated</u>						

*She is now in good condition and entitled to remain as classed.*

Committee's Minute 18<sup>th</sup> March, 1879.

Character assigned 100A

Senhouse Martindale  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18