

ANNUAL SURVEYS.

22902

No. Survey held at London Date, first Survey 10.3.79 Last Survey 10.3.79
 No. in on the S. S. "Kaieteur" Master Teisk
 Reg. Book. 888 Tonnage 1284 Built at Hartlepool When built 1876-11 mo
77 By whom built Withy Owners Steel, Young & Co
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Millwall Dry Dock

Last Survey, No. 20972 Port of London

Classed 90A.1.
 Years assigned. 4.78
 Character in Register Book.

Present Condition of the

Decks good
 Waterways do
 Comings do
 Upper Deck Beams & Fastenings do
 Lower Deck Beams & Fastenings do
 Planksheers do
 Sheerstrakes do
 Topsides do
 Wales do
 Plating (Bottom) and Counter do

Rufts where seen, good
 Breasthooks and Stemson do
 Transoms, Pointers, and Crutches do
 Timbers of the Frame at the Openings do
 Ditto ditto at other places do
 Keelsons where seen, good
Stringers do
 Ceiling do
 Rudder good
 Copper or Y.M. When put on
 Caulking of
 Bottom, Deck, & Waterways good

Windlass and Capstan good
 Pumps do
 Boats do
 Masts, Yards, &c. do
 Condition, how ascertained from deck
 Sails well found
 Anchors, No. of 3 B, 1 F & 2 K
 Cables complete
 Hawser and Warps good & suff.
 Standing and Running Rigging do

Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers do Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c. This vessel has been placed in dry dock and bottom examined and recoated with composition. Hold examined where possible, and found in good condition, and the vessel is, in my opinion, eligible to remain as classed.

Committee's Minute 18th March, 1879.

Character assigned 90A.1
TRW

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at London Date, first Survey 18.2.79 Last Survey 13.3.79 18
 No. in on the S. "British Stationer" Master Malony
 Reg. Book. 773 Tonnage 1222 Built at Liverpool When built 1867. 4 mo
773 By whom built Royden Owners British Ship Owners Co
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Canal Dry Dock & afloat

Last Survey, No. 19824 Port of London

Classed 90A.1.
 Years assigned. 12.77
 Character in Register Book.

Present Condition of the

Decks good
 Waterways do
 Comings do
 Upper Deck Beams & Fastenings do
 Lower Deck Beams & Fastenings do
 Planksheers do
 Sheerstrakes do
 Topsides do
 Wales do
 Plating (Bottom) and Counter do

Rufts wh. seen, good
 Breasthooks and Stemson do
 Transoms, Pointers, and Crutches do
 Timbers of the Frame at the Openings do
 Ditto ditto at other places do
 Keelsons where seen good
Stringers do
 Ceiling do
 Rudder good
 Copper or Y.M. When put on
 Caulking of
 Bottom, Deck, & Waterways good

Windlass and Capstan good
 Pumps do
 Boats do
 Masts, Yards, &c. do
 Condition, how ascertained from deck
 Sails well found
 Anchors, No. of 3 B, 1 F & 2 K
 Cables complete
 Hawser and Warps good & suff.
 Standing and Running Rigging good

Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers do Cargo and Main Hatchways good Hatches do

General Observations, Opinion as to Class, &c. This vessel has been placed in dry dock and bottom examined and recoated with composition. Hold examined where possible, and found in good condition, and the vessel is, in my opinion, eligible to remain as classed.

Committee's Minute 18th March, 1879.

Character assigned 90A.1
TRW

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18