

ANNUAL SURVEYS. 22903

No. 2639⁵ Survey held at Liverpool Date, first Survey Mar 10th Last Survey Mar 11th 1879
 No. in on the Ship "Lake Superior" Master N. Stewart
 Reg. Book. 169 Tonnage 1274 Built at Greenock When built 1868 - 12 mo.
 By whom built Steele Owners Canada Sh. Co. (Lim)
 Port belonging to Montreal Destined Voyage Montreal
 If Surveyed Afloat or in Dry Dock Clarence Dry Dock

Last Survey, No. 17523 Port of Ron Classed S.S. Lw N°2-76. Years assigned. 12-76. Character in Register Book. *AI
 Present Condition of the Decks Good Treennails Rivets. Good
 Waterways " Breasthooks and Stems "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shells "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Cement When put on 68 1/2
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Good

Bottom sighted cleaned and coated with paint and the vessel being now in a good & efficient condition, is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool March 18th 1879. Character assigned *AI Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) 18

No. ✓ Survey held at Liverpool Date, first Survey Feb 26th Last Survey Feb 26th 1879
 No. in on the Ship "Glenlogan" Master O. M. Ludvig
 Reg. Book. 475 Tonnage 589 Built at Barrow When built 1877 - 8 mo.
 By whom built Barrow Co. Owners S. Johnston & Co
 Port belonging to Liverpool Destined Voyage St Johns Newfoundland
 If Surveyed Afloat or in Dry Dock Clarence Dry Dock

Last Survey, No. 19469 Port of Ron Classed 100 AI Years assigned. 10-77. Character in Register Book. *AI
 Present Condition of the Decks Good Treennails Rivets. Good
 Waterways " Breasthooks and Stems "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shells "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Cem. When put on 77
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Good

Bottom sighted cleaned and coated with paint, and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool March 18th 1879. Character assigned 100 AI Surveyor to Lloyd's Register of British and Foreign Shipping. Certificate (if required) 18



Lake Superior

Glen Logan

26395



© 2019

Lloyd's Register
Foundation