

REPORT of SURVEY for REPAIRS, &c.

22947

37576

Recd 15.10.78

No.

No. in
Reg. Book.

Survey held at

London

Date, first Survey 27th Sept

Last Survey 1st Oct 1878

on the

S. S. "Lucien"

Master

Sangster

YEAR.

MONTH.

TONNAGE under Tonnage Deck 271

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Gr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St' mer, cut on Bm.

284

178

Built at

Glasgow

When built

1854

Owners

W. B. Thompson

Port belonging to

Lundee

Residence

By whom built

Destined Voyage

If Surveyed Afloat or in Dry Dock

River afloat

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

19316

Port

Ron

Classed

100 A.1.

L.L. Num. 23-76.

9-77.

REPAIRS, OR EXAMINATION AS PER RULE

Damage Repairs

On Starboard Bow one broken inside plate taken out and renewed, outside plate above it, taken off and replaced.

Cause of Repairs to be clearly stated.

Present Condition of the

Decks

Good

Waterways

Good

Comings

Good

Upper Deck Beams & Fastenings

Good

Lower Deck Beams & Fastenings

Good

Planksheers

Good

Sheerstrakes

Good

Topsides

Good

Wales

Good

Plank (Bottom) and Counter

Good

Treenails

Good

Breasthooks and Stenson

Good

Transoms, Pointers, and Crutches

Good

Timbers of the Frame at the openings

Good

Ditto Ditto at other places

Good

Keelsons

Good

Clamps and Shells

Good

Ceiling

Good

Rudder

Good

Copper

When put on

Good

Bottom, Deck, & Waterways

Good

Windlass and Capstan

Good

Pumps

Good

Boats

Good

Masts, Yards, &c.

Good

Condition, how ascertained

Turned back

Sails

Good

Anchors No. of

2. 1st 10 lb 1 kg

Cables

Good

Hawsers and Warps

Good

Standing & Running Rigging

Good

Engine Room Skylights

Good

Coal Bunker, Openings, Lids, &c.

Good

Scuppers

Good

Cargo and Main Hatchways

Good

Hatches

General Observations, Opinion as to Class, &c.

This vessel is now in good and efficient condition and in my opinion eligible to remain as Classed.

The Amount of Entry Fee ...

£

received by me

Special

£

19th Oct 1878

Certificate (if required) ...

£

5

(Travelling Expenses, if any, £)

Committee's Minute

18th October,

1878,

Character assigned

100 A.1.

W.B.

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register

Foundation

IRON 483-0211

(The Surveyors are requested not to write on or below the space for Committee's Minute.)